

MARCH, 1958

AMATEUR RADIO
AMATEUR RADIO
AMATEUR RADIO
AMATEUR RADIO

RADIO
RADIO
RADIO
RADIO
RADIO
RADIO
RADIO
RADIO
RADIO



AEGIS

TESTED COMPONENTS

Made in Australia

FOR AUSTRALIAN CONDITIONS

AEGIS POWER-LEAD T.V. FILTER

FILTERS OUT ELECTRICAL INTERFERENCE at T.V. frequencies!

Type LF-1TV: Rating 240v.—2a. maximum (500 watts). Tested under exacting conditions and proved thoroughly reliable. May be used with appliances fed from two or three core power leads. £2

Retails at

And for the **HI-FI ENTHUSIAST**
who wants to build his own **HI-FI UNIT!**

AEGIS Mullard "5-10"

HIGH FIDELITY AMPLIFIER

Rated power output 10 watts (maximum 12-13w.). Frequency plus or minus 0.5 db, 10 c/s. to 20,000 c/s.

Control panel: 12" x 3" x 1 1/4"; Amplifier: 11 1/4" x 6 1/4". £59

Retails at



AEGIS FIDELITY TUNER Mark 2

Latest model with ventilated shield, satin-gold backed plastic front and symmetrically placed knobs. Power supply drawn from existing power amplifier, preferably Aegis "5-10" (voltage dropping £32/17/6 adaptors available). Retails at



ALL AEGIS, T.V., HI-FIDELITY AND RADIO COMPONENTS available at . . .

J. H. MAGRATH & Co. Pty. Ltd.

208 LITTLE LONSDALE STREET, MELBOURNE, VIC.

Phone: FB 3731

1/6

AMATEUR RADIO

"HAM" RADIO SUPPLIERS

(KEN MILLBOURN, PROP.)

5A MELVILLE STREET, HAWTHORN, VICTORIA

North Balwyn Tram Passes Corner, near Vogue Theatre.

Phone: WM 6465

Money Orders and Postal Notes payable North Hawthorn P.O. Packing Charge on all goods over 10 lbs. in weight, 5/- extra.

NOTE THESE VALVE PRICES

Look at these Bargain Priced NEW VALVES—

1B3 .. 2/6	6N7 .. 10/-	7N7 .. 5/-	829B .. £5
1K4 .. 5/-	6N8 .. 15/-	7W7 .. 2/6	954 .. 5/-
1K3 .. 10/-	6NC7 .. 10/-	12AH7 .. 7/6	955 .. 5/-
1Q8 .. 5/-	6SF7 .. 12/6	12K6 .. 7/6	100TH .. 35/-
2A5 .. 10/-	6SH7G .. 4/-	12L5 .. 7/6	CV66 .. 5/-
3Q5 .. 7/6	6SJ7GT 12/6	12SF7 .. 10/-	EA50 .. 2/6
6AC05 .. 10/-	6S87 .. 12/6	12SG7 .. 10/-	EK34 .. 5/-
6AJ5 .. 10/-	6U7 .. 10/-	12SK7 .. 10/-	VR100 .. 5/-
6B4 .. 12/6	6SH7G 4/-	12SN7 .. 12/6	VR101 .. 5/-
6C8 .. 7/6	6V6GT 12/6	12SQ7 .. 2/6	VR102 .. 5/-
6E5 .. 10/-	7A6 .. 5/-	12SQGT 2/6	VR103 .. 5/-
6K6 .. 7/6	7C5 .. 5/-	12SR7 12/6	VR150 12/6
6K7G .. 5/-	7C7 .. 2/6	897 .. 20/-	VT50 .. 2/6
6L7 .. 10/-	7F7 .. 5/-	815 .. 35/-	VT52 .. 10/-

C.R. Tubes—5FP7 (U.S.A. 5FP1) 5/- each

1C7 .. 3/- each or 7 for £1	12SF7 10/- each or 3 for £1
2X2 7/6 each or 3 for £1	CV66 (RL37) 5/- ea. 5 for £1
6AC7 3/11 each or 7 for £1	EA50 2/6 each or 10 for £1
6H6Gs £1 a dozen	EF50 3/6 each or 7 for £1
6K7G 5/- each or 5 for £1	EF50 valve sockets, 3/6 ea.
6SH7 5/- each or 5 for £1	RK34 5/- each or 5 for £1
6SH7GT 4/- each or 6 for £1	VR57/EK2 10/- each
7C7 2/6 each or 10 for £1	VT501 7/6 each or 3 for £1
7F7 5/- each or 5 for £1	VT127 4/11 each or 5 for £1
954, 955 5/- ea. or 5 for £1	Local valve sockets, 1/6 ea.

New Valves—VR53/EF39, direct replacement for 6U7. High gain, low noise. 5/- each or five for £1.

THIS MONTH'S SPECIAL

Co-axial Cable, 80 ohm, in 100 yard rolls. 1/9 yard or £7/10/0 per 100 yard roll.

Aust. Wavemeter, Type AVB1, high freq., 145-165 Mc. approx. Valve line-up: 958 diode, connected into two type 1N35 cascade connected. D.C. amp., complete with spare set of valves and 3" 0-1 Ma. meter. Circuit enclosed. Contained in flat grey metal carrying case. Packed ready for rail, £5/17/6

U.S.A. I.F.F. Units, complete with Valves and Genemotor, £5/17/6. Less Genemotor, £4/17/6.

Midget Ceramic Trimmers, 3 to 55 pF. 1/-

Teletone Octal Valve Sockets 1/- each
Shielded Wire, single, American 1/6 yard

Meters—0-0.35 and 0-1 Amp. R.F., FS3 and 101 type 10/- ea.
Meters—0-500 microamp., 1 1/2" diam., flush mounting 30/-
Meters—0-30 Ma., 2 1/2" round type, American 40/-
Meters—0-100 Ma. 2" square, sealed 0-300, new £1
Meters—0-40 amp. A.C. 2 1/2" round type 25/-
Meters—0-20v., A.C. 2 1/2" round type, new 25/-

Relays—S.P.D.T., 24 volt, 3,500 ohms 7/6
S.P.D.T., 24 volt, 6,500 ohms 7/6
12 volt, 250 ohms 7/6
P.M.G. Type, 500 ohms 7/6
P.M.G. Type, 500 plus 500 ohms 7/6

W.I.A. Latest Call Books and Log Books always on hand.

American Loran Receiver R9A-APN4, 16 valves. Part of Loran Indicator. Equipment contains 3 6B4s, 1 5U4, 1 VR105, 2 2X2s, 1 6SJ7, 4 6SK7s, 1 6H6, 1 6SN7, 1 6SL7, 1 6SA7, lots useful parts. New in case. No packing charge. Gift at £7/10/-

AT5 Transmitters, less valves and dust covers £3

SCR522 American Transceiver. Frequency: 100 to 150 Mc. In clean condition, less valves £10

SCR522 Receivers, less valves £5

SCR522 Transmitters, less valves £5

BC733D Crystal Locked Receiver, tuning range 108-120 Mc. I.F. 6.9 Mc. Valve line-up: three 717As, two 12SG7s, one 12SH7, two 12SR7s, one 12SQ7, one 12A6. Also contains six miniature relays. Packed ready for rail. Gift at £5/17/6

108 Mark III. Portable Transceiver, complete with valves, less headphones, aerial and microphone £7/10/0

Co-ax Cable, 100 ohm, any length 2/- yard

Co-ax Plugs and Sockets, American Ampenol 5/- pair

Co-ax Right-Angle Plugs, American Ampenol 2/6 each

Command Receiver Right-Hand Drives 2/6

Command Receiver Flexible Drives, 12 ft. long 10/-

LARGE STOCK OF CRYSTALS

515 Kc. and 455 Kc. Crystals £3 each

3.5 Mc. Marker Crystals, latest miniature type complete with socket £2/10/-

Amateur Band Crystals, any frequency £2

Gold Plated Marker and Commercial Crystals, price on request.

Delivery in seven days.

List of Crystal Frequencies appeared in last month's advert.

No. 19 Genemotors £2/10/0

No. 11 Genemotors, Low Power £2

No. 11 Genemotors, High Power 17/6

ARS Vernier Dials, Low and High Frequency Bands, new 30/-
Calibrated Perspect Dials only 5/-

APX1 12v. and 24v. Shunt Motors, ideal for Small Beams.
Works on A.C., new £1/10/0

APX1 Chassis, top deck, containing 28 Miniature Ceramic 7-pin Valve Sockets, Condensers, Resistors, etc., etc. A good buy at £2/5/0; postage 5/- extra

Screwdriver Roll-up Kits, well known make. Contains three Standard, two Recessed Screwdrivers. Eargain 15/-

P.M.G. Key Switches, two-way 10/6

AR8/AT5 Cables, 12 ft. long 10/0

Type "S" Power Supply. 230 volt AC. Good condition. Personal Shoppers only £25

AT21 Power Supply, 230 volt AC. Good condition £25

Genemotors, Windcharger, 19v. 3.8 amp. input, output 405v. 0.095 amp. When 12v. input applied, 250v. output. £3/5/0

English Filter Chokes, small type, 40 Ma. 100 ohm resist. 3/6

EDITOR:

J. G. MARSLAND, VK3NY.

TECHNICAL EDITOR:

K. E. PINCOTT, VK3AFJ.

NOTES EDITOR:

V. M. JONES, VK3YE.

TECHNICAL STAFF:

J. C. DUNCAN, VK3VZ.

D. A. NORMAN, VK3UC.

R. S. FISHER, VK3OM.

ADVERTISING REPRESENTATIVE:

BEATRICE TOUZEAU,
86 Collins St., Melbourne, C.I.
Telephone: MF 4505.

PRINTERS:

"RICHMOND CHRONICLE"
Shakespeare St., Richmond, E.I.
Telephone: JB 2419.

MSS. and Magazine Correspondence should be forwarded to the Editor, "Amateur Radio," C.O.R. House, 191 Queen Street, Melbourne, C.I., on or before the 8th of each month.

Subscription rate in Australia is 18/- per annum, in advance (post paid) and A£1/1/- in all other countries.

Wireless Institute of Australia
(Victorian Division) Rooms' Phone
Number is MY 1087.

THE CONTENTS

Amateur Television—Part One ..	2
Who's Afraid of a Receiver?	7
Correspondence	10
Technical Correspondence	11
QSL Cards	13
Convention at Urunga	13
W.I.C.E.N. Notes	13
Book Review:	
U.h.f. Tubes for Communica-	
tion and Measuring Equip-	
ment	14
Tubes for Computers	14
Tube Selection Guide	14
YL Corner	14
Valve Data:	
6CB6—Sharp Cut-off Pentode ..	14
Amateur Call Signs	15
DX	16
Prediction Chart for March '58 ..	17
DXCC Listing	17
VHF	18
Notes	20

Published by the Wireless Institute of Australia,
C.O.R. House, 191 Queen Street,
Melbourne, C.I.

EDITORIAL



High Power and Component Parts

After the cessation of hostilities at the end of World War II, millions of pounds worth of surplus equipment became available on the disposal market—equipment which in normal times would be beyond the financial means of the average Amateur—and amongst this "gold mine" was equipment and components built to magnificent standards but in many cases well above the ratings required for the construction of Amateur phone and c.w. transmitters with the maximum input permitted to be used by the Australian Amateur.

No one can criticise the man who designs his equipment with a good margin of safety, indeed he is to be congratulated, not only for providing safety, voltage wise and insulation wise for himself, but for others who might come in contact with his equipment also. But the regulations governing the operation of Amateur stations did not provide for the use of such components particularly, which when used together could exceed the licensed maximum input, and the result was that many Amateurs who purchased this equipment were in trouble with Radio Inspectors from the Postmaster-General's Department who regularly inspect Amateur stations in accordance with the Wireless Telegraphy Act in the same way that commercial stations are inspected, and currently television stations also.

The Wireless Institute of Australia made representations on behalf of licensed Amateurs for a clear-cut policy on this matter and agreement was reached with the Wireless Branch of the Postmaster-General's Department that a combination of high power rating components could be used providing the licensed maximum input to the final stage of a transmitter could not be exceeded by other than a major modification to the installation. Despite this, there have been cases where Departmental Inspectors have continued to enforce the earlier regulation to the embarrassment and confusion of the Amateurs concerned. This will now cease! The Handbook for the Guidance of Operators of Amateur Stations is being reprinted and will shortly be available to

Amateurs through the usual Book-sellers or direct from the Postmaster-General's Department. Other concessions granted to Australian Amateurs due to W.I.A. representations will be included and it is every Amateur's duty to obtain a copy and keep it handy at his operating position in the "shack".

Concerning the use of high power components, Paragraph 62 of this Handbook reads as follows:—

"Transmitting apparatus installed in an Amateur Station must be operated in such a manner as not to exceed the power authorised. Single components such as valves, transformers, etc., capable of handling power in excess of that licensed are permitted without restriction in Amateur Station transmitters, but where a combination of such components is in use a method satisfactory to the Department must be employed to ensure that the d.c. power input to the anode of the final transmitter stage cannot exceed that authorised. For example, power supply transformer tapings should be arranged in such a way as to obviate without a major alteration the possibility of an increase of voltage beyond that necessary to supply the licensed power."

Unlike operators of bushfire fighting transmitting equipment, fishing craft and other small ships transmitters, taxi services, etc., the Amateur is a qualified technical person in his own right and is a licensed member of a recognised transmitting service. This service has never let the country down during times of either Civil or National emergency and with its members' "know-how" equipment is designed and constructed in accordance with any regulations or specifications.

Let us keep it this way! Paragraph 62 permits you to construct and operate your equipment to standards previously unobtainable. Don't abuse it! Those who do cannot expect the assistance or sympathy of the W.I.A. Administration. The old "bogy" of the use of high power components is now history. It will be kept that way for the betterment of Amateur Radio. The way it is kept is up to you—the Licensed Amateur.

FEDERAL EXECUTIVE

AMATEUR TELEVISION

PART ONE

BY E. E. CORNELIUS,* VK6EC/T

WITH the commencement of Television in N.S.W. and Victoria, and its extension to the other capital cities in the next year or so, an upsurge of interest in Amateur Television may be expected. A broadcast service means receivers, and a simple converter on the front end of a standard t.v. receiver provides one end of an Amateur circuit. All the commercial components available are designed around our 625 line system. A broadcast service too, can be pressed into service to provide the Amateur's source of synchronising signals.

For these reasons therefore, I suggest that Amateur t.v. in Australia should concentrate on 625 line standards, with both video and sound paralleling the broadcast service. The sound carrier should be 5.5 Mc. above the vision carrier, f.m., with 80 Kc. deviation. Then any commercial receiver, or home-brew either for that matter, can be pressed into service as a high quality monitor, or Amateur receiver.

This series will describe equipment for 625 lines, to Australian standards. The lowest, and therefore easiest band on which we may operate is 288 to 296 Mc. I therefore recommend that we set up a standard t.v. channel within that band—

- i.e. Vision carrier 290.25 Mc.
- Sound carrier 295.75 Mc.

With vestigial sideband transmission, the video does not extend below 289 Mc., leaving one megacycle of the band undisturbed. The transmitter to be described conforms to this plan.

The basic equipment needed can most easily be shown by the block diagram in Fig. 1. Variations of the scheme will be elaborated as each unit is described.




FIG. 1—BLOCK SCHEMATIC-CAMERA CHAIN

Vidicon type camera tubes are now available at reasonable cost. They are satisfactory for Amateur use. Cost—approximately £A38 landed here.

With this tube, the Amateur can build a simple t.v. transmission chain, or can make elaborate equipment approaching commercial broadcast standards. For a

start, a flying spot scanner will serve to generate signals from transparencies, slides or film negatives. But soon the desire for "real pictures" will develop, and a camera will be projected. The method for obtaining one of these tubes will be outlined in Part Two.

This series of articles will be built around specific circuits, which work well, and can be duplicated if you wish.




FIG. 2.—SYNC. GEN. BLOCK SCHEMATIC

Some of the data is basic, while some will be subject to your own convenience, pocket and what you have. The results obtained with the equipment to be described are in conformity with Australian commercial standards, with full 5 Mc. video bandwidth. To obtain this the equipment is fairly ambitious, but simplifications will be outlined, but with correspondingly lowered performance.

4. **Video Mixer** enabling four picture channels to be mixed, and also inserting blanking and sync. With minor additions, this unit may be used in place of the camera control.
5. **Master Monitor** with a 12" picture monitor, using a VCR140, and simultaneous twin waveform monitors at both line and frame rates, using 5BP1s. Pulse cross display facilities are provided, and it can be used as a transmitter monitor, with detector diode and amplifier. Input required is 1.4 volts composite video.
6. **Video Transmitter** on 290.25 Mc., with 10 watts peak white output from a 6Q603/12, vestigial sideband filter, and broad band antenna with 10 db. gain.
7. **Regulated Power Supplies**—These are a must for most units.
8. **Video Oscilloscope**, grating generator, test charts and testing methods.

Before attempting to build a camera, other equipment will be needed, and the total number of tubes required will be considerable. I will describe fairly complex equipment with performance to C.C.I.R. standards, that you can duplicate if you wish. I will also show simplifications, although performance will suffer somewhat.

But you can make good pictures with comparatively simple equipment so do not be alarmed at the complexity of that described, as they have been designed to duplicate all broadcast t.v. functions, and much is not essential, although perhaps desirable.

To duplicate the equipment described is a project for a couple of years of work, but Amateur t.v. lends itself to club or community effort. A group of

* 157 Wood Street, Inglewood, W.A.

MODEL "1XA" CRYSTAL MICROPHONE INSERT



AUSTRALIAN MADE — — FOR AUSTRALIAN CONDITIONS



FITTED WITH PLATED REAR SHIELD TO ELIMINATE HUM PICK-UP

- Patented crystal unit guarantees outstanding efficiency and performance.
- Protected against ingress of moisture with approved moisture sealed crystal element.
- Small — compact — lightweight — durable.
- Will not blast from close speaking.
- Precision engineering ensures realistic reproduction and high output with long life and dependable operation.

- The only unit available with a genuine sintered metal filter.
- Good high frequency response ensures excellent speech reproduction.
- Aluminium diaphragm mechanically protected and frequency controlled by "Zephyr" filter.
- Australian made throughout.
- Only carefully selected cements used throughout, to suit Australian climatic conditions.

TECHNICAL DETAILS

Rochelle salt crystal microphones are perhaps the most widely used for all types of service where quality speech and music reproduction at high output levels is a requirement. They are dependable in performance and when fitted with the appropriate "Zephyr" filter, their frequency response may be adjusted to suit any application or requirement.

This crystal microphone requires to be terminated with a high value parallel load of the order of 1 to 5 megohms for best results.

The mass of the moving parts is small, hence the sensitivity is high and a high efficiency is achieved.

Light gauge solder lugs are provided so that excessive heat in soldering will not be transmitted to the crystal element.

When mounted in a microphone cage, it is recommended that the insert be suspended in rubber, to eliminate shock and vibration.

One of the connecting lugs is directly connected to the case and care should be taken to solder the metal shield of the microphone cable to this solder lug, keeping the unscreened portion of the centre conductor as short as possible to eliminate hum pick-up.

All crystal elements are mounted on high grade suspension pillars, being fixed thereto with a good quality cement, thus ensuring stability and long life.

Case $1\frac{1}{2}$ " diameter (rear), $\frac{3}{8}$ " thickness, 1-13/16" overall diameter (front) with filter fitted.

Frequency Response = 60-8,500 c.p.s.
Output Level = -45 db (0 db = 1 volt/dyne/cm²)
Impedance = Model 1XA Grid 1 — 5 megohms.



Approximate Frequency Response Curve

AVAILABLE FROM ALL LEADING TRADE HOUSES

ZEPHYR PRODUCTS PTY. LTD.

58 HIGH STREET, GLEN IRIS, S.E.6, VIC.
Phone: BL 1300

two, three or more Amateurs can build a system in reasonable time, and share the work and expense. The simpler equipment is well within the capabilities of the average man.

THE SYNCHRONISING SIGNAL GENERATOR

This is the heart of the system, generating accurately timed pulse trains to hold all transmitting equipment in exact synchronism, and provide the transmitted sync. signal for all receivers. See Fig. 2.

There are four outputs:—

1. Line drive, for all line time bases and keyed clamps at the transmitter end, at 15,625 pps. of 5.6 usec. duration, leading sync. by 2.8 usec.
2. Frame drive for all transmitter frame time bases, 50 pps. of 7½ lines duration.
3. Composite blanking for blanking of flyback in all picture tubes except the viewfinder. Line duration 11.6 usec. frame 18.22 lines.
4. Composite sync. for transmission with the blanked picture signals for sync. separation in all receivers. To Australian specifications.

It is easy, but not always convenient, to extract composite sync. from a sync. separator operating on a broadcast transmission. A good sync. separator will extract clean sync. signals, and these may be used to synchronise free running time bases in the camera, etc. Alternatively, the sync. can be used to control blocking oscillators or multi-vibrators which will generate line and frame driving pulses for use by driven time bases. Combining the two pulse trains will give a composite blanking pulse train, but the front porch will require more complex circuitry.

The sync. generator whose circuit is shown in Fig. 3 uses a 6SN7 (V1) as a free running blocking oscillator, and buffer feeding a delay line for timing of the equalising, line sync., line drive, line blanking and field sync. pulses. The buffer also feeds a 625 to 1 frequency divider, V2, 3, 4 and 5, using two phantastron circuits, each dividing by 25. The second phantastron delivers 50 c.p.s. pulses (4), which are used via a buffer (V11B) to trigger the three 50 cycle multivibrators V13, 15 and 16. The waveforms shown on the diagram are numbered, and will be referred to by the number in brackets as (4) above. The frequency of the pulse train is shown at the top of each oscillogram.

Composite Blanking

On receipt of the negative 50 cycle trigger pulse (5) from V11B, V13B is cut off, V13A conducts and a positive pulse (6A) is emitted from the cathode. That is the field blanking pulse, and is adjusted to 18 to 22 lines duration.

Similarly, V1A receives positive triggers (21) from the delay line at 31,250 pps., with each alternate pulse striking on a 15,625 pps. pulse from V20, via the resistor network. Only the alternate pulses will overcome the bias of V11A, causing it to conduct, and the negative trigger from its plate, cutting off V12A, causes V12B to conduct, and emit a train of line blanking pulses (6B). Their duration is adjusted to 11.6 usec.

The common cathode connection to V13A feeds composite line and field blanking pulses to the diode clipper

and the output tube V14. This tube is normally cut off, with anode at earth potential, but on conduction at each input pulse, a 4 volts negative pulse train is delivered to a 75 ohm load (7A) (7B).

Composite Sync.

Tube V15 (a) provides field driving pulses to the vertical drive output tube V18.

(b) In co-ordination with V17, the 2½ line gate MV, and V16, the vertical pulse delay MV, keys in 5 pre-equalising pulses, and 5 post-equalising pulses in the composite sync. circuit. This is done via V6B, the equalising pulse gate, which allows the equalising pulse MV (V9) to operate only while its cathode is not positive, i.e., when V15B and V17A are cut off. The sequence is as follows:

V13B, V15B and V16B are normally conducting, V15B cutting off V6B the equalising gate, and paralysing V9, the equalising MV. The negative trigger pulse from V11B cuts off V15B, allowing V6B to conduct, opening the gate to the 31,250 pps. triggers from the delay line to V9, which then generates equalising pulses.

At the same time V15A conducts, its cathode runs positive (8), cuts off V6A, the sync. gate, and closes down the line sync. MV (V8). Also at this instant, the 50 pps. trigger pulse cuts off V16B, readying it for cycling 2½ lines later. At the end of 2½ lines (5 equalising pulses), V16 cycles, V16B conducts again, its plate going negative, and via the diode, cutting off V17B, allowing V7A to conduct, gating in the vertical sync. pulses, and gating out the equalising pulses via V17A and V6B (9).

After 2½ more lines, the vertical sync. period, V16 restores to normal, gating out the vertical sync. pulses, and gating in equalising pulses again. After a total of 7½ lines, V15 cycles, V15A cuts off, V6A conducts, and the horizontal sync. MV starts up again until the next trigger.

The sequence thus is, horizontal sync. pulses till the trigger, then 5 equalising pulses, 5 vertical sync. pulses, 5 equalising pulses, and then the sync. pulses again. All done by the common cathode connections of the enabling MV's, and the gates, V6A, V6B and V7A. A common cathode connection between the H. sync., V. sync., and equalising multivibrators, goes to the composite sync. output tube (19), clipping in the GEX34, and the output tube grid, with the sync. train available at the anode of V19, at 4 volts p/p. in 75 ohms, negative going (20). No coupling capacitor is needed, as the tube is normally cut off by grid current bias, and the anode at earth potential.

The line sync. MV (V8) gets its triggers similarly to the blanking MV, but via V6A, at 15,625 pps. (22). The equalising and vertical sync. MV's get their triggers direct from the delay line at 31,250 pps., via V7A and V6B. The pulses are adjusted to correct durations by the corresponding potentiometers in the MV grid circuits.

Line Drive

The line driving pulses at 15,625 pps. should precede blanking and sync., to overcome camera cable delay, so triggers are fed from the first tapping on the delay line (14), via V7B to the

grid of V20A, normally cut off. This MV has constants such that it will not cycle at trigger rate of 31,250 pps., but will do so at 15,625 pps. The potentiometers are adjusted for correct division, to line rate, and for correct driving pulse width, from 4 to 7 usec. (15). This driving pulse train is delivered by output tube V21 (16). The drive pulses are also fed back to the resistor network in the delay line, for addition to the 31,250 pulses, to provide the trigger pulses for the line sync. (22) and line blanking MV's (21).

Frame Drive

An output of the 7½ line MV (17) is used for frame drive, via its output tube V18 (18).

SIMPLIFICATIONS

This unit will deliver outputs to C.C.I.R. standards. For Amateur work this is not vital, and the whole of the composite sync. circuit can be omitted. The receiver will then trigger from the blanking pedestals, but with a tendency to picture "tearing" at the top, and erratic interlace due to lack of serrations in the vertical sync. pulse, and equalising pulses.

It will then be necessary to retain V1 to V5, the divider chain, V11, 12, 13 and 14 for blanking (and sync.). V13 can feed V18 for frame drive. The delay line can be omitted, but V20 will be required for 2:1 division. It may be feasible to combine the functions of V20 and V12. V20 will give line drive, as before.

CONSTRUCTION

There are no tricky parts in the construction, although the delay line may be unfamiliar. This consists of 14 identical inductors of 200 μH. each, in series, 1" apart, on a 1" dowel. The tapping points are shunted to earth by 200 pF. capacitors, with each end shunted by 100 pF. The delay per section is \sqrt{LC} (μH , pF, usec.) = 0.04 usec. Mine were wave wound, but you could scramble wind in slots in a 1" former (about 120 turns each). Match these windings, and mount the whole unit in a shielding box. The 200 pF. capacitors should be matched to 2% or better, but the actual value could be anywhere from 180 to 220 pF. For 200 pF. and 200 μH. the impedance of the line is 1,000 ohms. For other values it is $\sqrt{L/C}$, and best obtained by experiment after assembly. Feed 31,250 pulses to the line, and bridge a c.r.o. across the input to the line. Fit a carbon potentiometer of 5,000 ohms termination. Vary this for the clearest pulse display, measure its value, and fit a fixed resistor of the same value.

The blocking oscillator transformer for the master oscillator can be a line b.o. transformer from a receiver. This may need damping with a resistor across the secondary, to prevent a damped wave train from following the output pulse. As there is a lot of meat in this package, some thought on chassis layout will be well worth while. The pulses have rise times of the order of a few tenths of a microsecond, so will radiate strong harmonics. I suggest that the layout shown in Fig. 4 could be used as a guide. The whole unit can then be housed in a metal case 18" x 14" x 7", with the chassis mounted vertically in the case, tubes and controls on one side, wiring the




FIG. 4.
SYNC. GEN.
LAYOUT

other. Removable doors will enable easy access and alignment.

Adjustment

This really needs a good c.r.o., preferably with triggered sweep, but an orthodox unit can be used, with some limitations. First, set the master oscillator to 31,250 pps., by comparison with some known frequency standard. Always take test output from the buffer (1) so as not to disturb the frequency with your test prods. A wavemeter will make an excellent frequency standard—remember the output is rich in harmonics. Or you can use a c.r.o. comparison with an accurate audio oscillator.

To adjust the first phantastron divider, take output from the screen of V3 (2), via a 10,000 ohm resistor, hold this in sync. on the c.r.o., and spread it as wide as possible. Count the small downward pulses from leading edge to leading edge of the 1,250 pps. output pulses. Adjust the 2 meg. pot. in the grid circuit for a count of 25. If any kick back from V5, which is still un-synced upsets the display, open its plate supply till V3 counts correctly.

Now adjust V5 for a count of 25 also in a similar manner (3). Compare the output frequency with the 50 cycle mains. It should be very close, better than a quarter cycle. If not, check back again. Once adjusted, the phantastron is very stable, but the initial adjustment is tricky, although much easier with triggered sweep c.r.o.

Next to be adjusted is V20, for division by 2, and pulse width. Connect c.r.o. to plate of V20A, via a 10,000 ohm resistor, and adjust for division. Remove 10K resistor, connect to cathode, display two pulses (15), and measure distance from leading edge to leading edge. This is 64 usec. By proportion adjust the pulse width to about 5 usec. Now comes the H. sync. MV (V8). Make sure it is being triggered at 15,625 pps., not 31,250, and

then adjust pulse width to 5 usec. Similarly with V12, the H. blanking MV, adjust to 11.6 usec. If triggering is occurring at 31,250, adjust the bias, about -9 volts, by the 1K, 25K voltage divider at the input of the delay line.

For the vertical sync. MV (V10), allow it to run continuously by removing V17 pro. tem., and adjust the slot width to 5 usec. Similarly with V9, the equalising MV, remove V17 and V15, and adjust pulse width to 2.5 usec.

For adjustment of the 50 cycle MV's a triggered sweep is a great help. Obtain your 50 pps. trigger or sync. pulse from the trigger line (5), plate of V11B. Display the vertical sync. area of the composite sync. (19), and adjust V16 to give 5 pre-equalising pulses, V17 to give 5 vertical sync. blocks, and last, V15 to give 5 post-equalising pulses. Using a standard c.r.o., difficulty may be experienced maintaining sync. with

the considerable sweep expansion needed to open up the V. sync. area enough for counting the pulses.

The vertical blanking MV is adjusted by superposing some 31,250 or 15,625 pulses from the master oscillator, or appropriate MV, and counting either 36 to 44 pulses for triggered or 50 cycle sweep, or 18 to 22 sync. pulses for 25 cycle sweep. This is because trigger or 50 cycle sweep displays both fields interlaced, and the sync. rate pulses are apparently at 32 usec. intervals.

Critical Components

Generally speaking 10% components will serve, with the following exceptions, which will need to be checked by experiment. The counter chain grid resistors. These will all be off, if substitute tubes are used, and the circuit values shown are right for my 6SK7s. The low value capacitors in the MV's have been selected, and the nearest standard value shown. The 0.25 μ F. capacitors are not critical. The resistors in the voltage divider chain in the delay line may have to be adjusted on test. Use linear potentiometers throughout, otherwise one end of logarithmic types will be cramped. The delay line capacitors must be matched as outlined earlier. The tubes shown have been used because I had them. Any pentode with suppressor not tied internally to cathode will do for the phantastrons. 12AU7s may be used in place of the 6SN7s without alteration. 12AX7s with some attention to the small capacitors in the MV's.

Power Supply

That shown is satisfactory. As the negative supply has to deliver about 250 mA. for the few microseconds that all output tubes are conducting, during the V. sync. period, although average output is only 60 mA., the large 200 μ F. output capacitor in the filter is essential. The glow tube on the 150 volt negative bus is to make sure that no variations find their way into the bias circuits. Glow tube regulation of plus 150v. is quite satisfactory, as the current drain is constant at about 120 mA.

In this Part, I have described the most important unit, and the most difficult. In Part Two I will describe the camera and viewfinder.

Duralumin Aluminium Alloy Tubing for Radio Aerials

★ LIGHT ★ STRONG ★ NON-CORROSIVE

STOCKS NOW AVAILABLE FOR IMMEDIATE DELIVERY

ALL DIAMETERS— $\frac{1}{4}$ " TO 3"

RECOMMENDED FOR TELEVISION AND BEAM AERIALS

Price List on Request

STOCKISTS OF SHEETS—ALL SIZES AND GAUGES

GUNNERSSEN ALLEN METALS

PTY. LTD.

88-92 YARRA BANK ROAD, SOUTH MELBOURNE

Phone: MX 4624 (9 lines)

Telegrams: "Metals," Melbourne.

Who's Afraid of a Receiver?

BY BYRON GOODMAN, WIDX

THE sad ungrammatical answer to the above question is "Too many." Ask the Hams of any representative group how many of them ever dig into their receivers for any reason whatsoever, and you're likely to find that most of them are literally scared to death of the mere thought of action. This isn't just an idea we're pulling out of the air; be perfectly honest about it and you will admit we're describing the situation as it is.

Perhaps you're beginning to wonder why anyone should want to touch a receiver. After all, a good receiver should be in top working condition all the time, shouldn't it? Phooey! Why should it? Even the best receivers can stand touching up from time to time. Years ago the author was visiting a W2 friend of his who claimed he had a good location for 7 Mc. DX but it was no good for 14 Mc., and he had the cards to prove it. This we had to see, because it just didn't make sense. Listening around on the two bands did indeed show a marked difference in the way the bands sounded; 40 was "hot" and 20 was dead. The W2 was a sharp one, and even had a small antenna coupler between antenna and receiver.

When asked if he had checked the front-end alignment on 20, our friend replied that the receiver trimmers were sealed and the guarantee would be void if he broke the seal. (You old timers will recognise the receiver.) As we took leave of our friend we went out on a limb and said, "Break the seals, align the front end, and watch 20 come alive." A few days later we got a card from him, admitting he had screwed up his courage, broken the seals and aligned the front end on 20. Our pal concluded by enumerating the several new countries he had worked on 20 (including a couple we could have used nicely!)

One more fr'instance. Less than a year ago a friend built a new preselector which he connected ahead of a current model of a good receiver. Our friend was lavish in his praise of the preselector's performance, claiming that 10 and 15 metre signals practically inaudible on the straight receiver were loud and clear when the preselector was hooked in. We couldn't believe the receiver was that bad, so we asked him to check the front-end alignment on 10 and 15. The subsequent red-faced report was that the preselector didn't do as much good as he thought; the receiver front end had been out of adjustment.

But if you had wanted the story of somebody's life you would have bought a copy of "True Confessions." You want to know about receiver-phobia. We just threw in the examples to show how two Hams, who weren't afraid to tackle their receivers, avoided holding to erroneous conclusions about frequency-sensitive locations and superlative preselectors.

● There is a growing tendency these days to accept a communications receiver as a strange piece of complicated gear with "innards" no one but a man from Mars should touch. WIDX diagnoses this condition as "receiver-phobia" and tells why and how to avoid catching it.

Let's examine the possible causes of receiver-phobia and then talk about cures and the benefits of shaking off the affliction. What's so sacred about a receiver? Why shouldn't any Ham worthy of the name tackle a receiver as readily as he will a transmitter? For one thing, many operators are afraid to touch a receiver because they're afraid they'll spoil the dial calibration. (This is the same dial calibration they grouse about because it isn't accurate to 100 cycles!) Then there is the fear that the receiver will be thrown so far out of alignment that no one would ever be able to put it back. And, last but not least, there is the Ham who throws up his hands on the basis that "the thing is just too darned complicated." We're not talking about making any extensive receiver modifications, so the old it-will-lose-its-resale-value argument doesn't apply.

Let's examine these "reasons" for not touching a receiver. Do you think some high-powered engineer lines up every receiver at the factory? Of course not. It's someone who was taught the job, and chances are he or she knows very little about receiver theory and design. He or she merely follows a set routine, not at all unlike the alignment procedure outlined in most instruction books. Throw the receiver too far out of alignment? You could only do that by changing something very drastically not by twisting a few trimmers. After all, most receivers coming off an assembly line are not close to alignment, except through chance or a complicated system of subassembly testing. Production receivers have to be brought into line by the hired hands mentioned above.

As for the last argument, "complicated" is a relative term. A hand-cranked phonograph is sheer magic to a native of OGS, but it is only a curiosity to any high-school student who has his room cluttered up with hi-fi gear. Sure, a modern receiver looks complicated to someone with no electronic background, but it uses tubes and components quite similar, except in size and shape, to those used in a transmitter. The wiring diagram is really no more complicated than that of a modern band-switching transmitter; the sad truth is simply that most of these schematics are laid out so poorly that they look ten times more involved than they really are. We don't suggest that the manufacturer does this deliberately to justify some of the current

prices; we suspect that worrying about clarifying the schematic in the instruction book is merely considered an unimportant waste of time. If so, it's too bad, because we might have a more technical breed of Ham if things were made a little easier for him at the start. If the schematics were laid out with fewer long leads running all around the drawing, and each stage were set off just slightly from the others, a tyro would have considerably less trouble following the signal through from antenna to output. And surely some of the switched circuits could be less complicated looking! Granted it takes some planning to organise a schematic so that it is relatively easy to follow, but it would be a big help to newcomer and old timer alike.

THE SOLUTION


There are two ways you can go about ridding yourself of receiver-phobia. The long, but more satisfying, way is to learn what makes receivers tick. Find out from various texts just what superheterodynes are, the principles behind them, and some of the variations (single and multiple conversion, various detectors). Learn to visualise what is happening in your receiver! as you tune across a signal; pay no attention to what the signal is saying, at least while you're analysing receiver operation. Visualise the actions of the controls as you observe the effects, and if you don't know the answers, go back to the texts.

But maybe you have only 60 or 70 more years to live, and you would like a short cut to curing your receiver-phobia. OK, take the plunge. Lift the lid! Don't touch anything yet; just dig into the instruction book and find the section where it talks about alignment. From the diagrams in the book and the lid-up receiver, locate a trimmer adjustment on an i.f. transformer. Check to make sure you have an alignment tool (insulated screwdriver or wrench). If you haven't, go out to a radio store and get one. Turn on the receiver and tune in a signal. Check the location of that i.f. trimmer adjustment against the book just once more, grit your teeth, and turn the adjustment a little! Nothing real serious will happen, except that the signal you had tuned in may get a little weaker (or stronger). You will find that you can peak a signal or drop it down by your adjustment of the i.f. trimmer. This is the same sort of operation you perform when you peak the drive in your transmitter, but this is a receiver and you've taken the big step. (Don't fool with crystal filters unless you know your stuff; they can be tricky.) And don't be like one fellow we heard of: his receiver was working too well so he tightened all of the loose screws, most of which were trimmers!

Again referring to the instruction book, read about front-end alignment

1 As described in McCoy's "Let's Listen", "QST", March, 1953.

*There are
no doubts
about THIS Double-V!*



... IT'S THE RESULT OF 20 YEARS

MANUFACTURING & RESEARCH EXPERIENCE!

**'BELLING-LEE' DOUBLE-V
T.V. AERIALS**

PERFECTED · PROVED · PREDOMINANT

Built into the "Belling-Lee" Double-V is every "know-how" learned over years in the laboratories and workshops of the "Belling-Lee" organisation in England, and now also in Australia—pioneers in T.V. aerial construction and originators of the Vee-Rod Double-V Aerial.

● AS A RESULT

- ★ Brilliant, unequalled performance—PROVED BY FIELD TESTS BY INDEPENDENT LABORATORIES.
- ★ MEASURED RELATIVE GAIN compared with that of half wavelength folded dipoles is: CH2, 1.5 db.; CH7 and 9, between 6 db. and 7 db. Compare these results with any other published figures and you will appreciate "Belling-Lee" superiority.

- ★ They are easy and fast to erect. Made of high-tensile aluminium alloy, they are EXTRA STRONG; they go straight up and stay up straight. They are corrosion-resistant, withstanding all climatic conditions.
- ★ Available in four alternative mountings—wall, chimney, flat roof or inside roof.
- ★ Every aerial is individually tested and GUARANTEED in writing for 12 months, your assurance that when you install "Belling-Lee" your first cost is your last.

*"BELLING-LEE"
is the proved
DOUBLE-V!*

'BELLING-LEE'
VEE-ROD DOUBLE-V
T.V. AERIAL SYSTEMS

SOLE AUSTRALIAN AGENTS:

AVAILABLE FROM YOUR REGULAR WHOLESALER.

R. H. CUNNINGHAM
PTY. LTD.

8 BROMHAM PLACE
RICHMOND, VIC.
JB 1614

16 ANGAS ST.
MEADOWBANK, N.S.W.
WY 0316

and repeat the experiment. You will find that trimmers on the r.f. and mixer circuits change the signal strength, while oscillator trimmers change the tuning and consequently, the dial setting for a given frequency.

CHECKING PERFORMANCE

One point that bothers many Amateurs, and rightly so, is how to determine when their receivers have deteriorated in performance. To some extent the ability to spot such things depends upon how much you want to learn about receivers and what happens inside them, but we can pass along a few simple checks and you can be your own judge as to whether or not you want to do something about them.

Take the matter of hearing the weak ones. This is described by Ham as "sensitivity" or "selectivity-to-noise ratio," but it means "hearing the weak ones." If your receiver has an antenna trimmer, as most of the current models do, the increase in noise you hear as you swing the trimmer through resonance (with the antenna connected) is a pretty fair measure of how good the front end of the receiver is. If you're in a noisy (electrically) location, the front end doesn't have to be as good as it does in a quiet location, because the local electrical noise is the limiting factor. Suspect the front-end alignment of your receiver if the noise does not peak up with the antenna trimmer the way it did when the receiver was new.

Many owners of two-dial complete-coverage receivers align the front ends of their receivers. In the Ham bands as soon as they get their receivers, to insure that the best performance is available where it will do the most good. In most cases this Ham-band alignment will not be the same as that described in the instruction book, but all it involves is touching up the trimmers on the r.f. and mixer coils when the receiver is tuned to the centre of the Ham band for which the band switch is set, with the antenna connected. Refer to the instruction book for the trimmer locations, don't touch the oscillator trimmer unless trimming the mixer pulls the receiver badly off calibration.

If the Ham band falls at the high capacity end of the band-set capacitor, as is true of the 20 meter band on a number of receivers, the trimmer capacitor should be touched. Instead, pull the r.f. and mixer coils into line by adjustment of the tuning slugs, if there are any. If there aren't any, you will need a "tuning wand" to check alignment at the low frequency end of a range. This is an insulated rod with a brass sleeve at one end and a powdered iron slug at the other. Pushing the brass end in or alongside the coil lowers the inductance, and bringing the iron end near raises the inductance. If bringing either end of the wand near the end of the active r.f. or mixer coil increases the strength of an incoming signal, it indicates that the circuit is not peaked for that frequency. In this case you can change the inductance of the coil by cementing a closed copper loop or a bit of powdered iron slug at an appropriate distance from the coil. Obviously, you don't have to modify

the inductance of the r.f. coil if it has an antenna trimmer across it, and probably the best addition to a receiver without an antenna trimmer would be such a trimmer. And, of course, trimming the inductance at the low frequency end will require resetting the trimmer at the high frequency end.

Checking frequency calibration is something every Ham should know, and it shouldn't be necessary to point out that a 100 Kc. crystal oscillator is a Ham's best friend for this little task. You can bring a receiver into fair calibration on one of its ranges by bending plates on the oscillator tuning capacitor, but it's a job only for a guy with patience and confidence.

We've already mentioned i.f. alignment; you just peak the trimmers of the i.f. transformers for maximum signal. If the receiver has a crystal filter and you use the filter lot, be sure that your test signal has been properly centered in the crystal filter before you touch up the i.f. trimmers. Do this by switching the filter in, the a.v.c. on and the b.f.o. off, and tuning slowly across a steady signal (a harmonic from your 100 Kc. calibrator makes a good one) for maximum S meter reading. If the receiver drifts or if the crystal filter is very sharp, it pays to "rock" the tuning a little while you touch up an i.f. trimmer. This merely means tuning back and forth through the peak to be sure that you are not slowly drifting off the peak.

If your receiver has no S meter, and you don't have a voltmeter that can be swung across the a.v.c. line temporarily to set as one, your only recourse is to turn on the b.f.o. and peak the i.f. trimmers by ear. Here again the "rocking" technique is suggested, to eliminate minor drifts of the oscillators.

RECEIVER FAULTS

We won't attempt to kid you into believing that brand new receivers do not have shortcomings, because some of them do. One has no right to expect an inexpensive receiver to do everything the expensive ones will. The inexpensive receivers have corners cut right and left, in an effort to bring the price down, but some of these omissions can be corrected by the owners. One fault you will sometimes find in the low-priced receivers is a change in frequency with a change in gain-control setting. This doesn't (or shouldn't) happen in a good receiver. Usually all it takes to correct it is to regulate the anode voltage on the high frequency oscillator and the screen voltage of the mixer (they're usually the same tube element unless a separate oscillator tube is used). On occasions, the b.f.o. may also require voltage stabilisation. If you have a receiver that has this characteristic of frequency change with change in gain, all it may need is the addition of a VR tube and dropping resistor of the right values. Check the receiver voltage chart for the proper value. If, for example, the required voltage is 85, you can get it from a

VR105 and a suitable dropping resistor. If the receiver already has a VR tube and still exhibits the trouble, make sure that (1) the VR tube is lit, and (2) the mixer screen voltage is regulated. (It isn't in all receivers.)

If the receiver seems to drift too much, you can try the dodge of propping up the lid, as pointed out in an earlier article.² Don't get any big ideas about putting in a compensating capacitor across the high frequency oscillator, unless you want to run a long series of tests. The trouble with temperature compensation is that you have to find a spot in the set where the temperature varies in the same way that the frequency does. Since the temperature drift may be caused by thermal changes in several components, you can see how tough your chances are of finding the magic spot. Shoot for reducing the temperature rise; your hair will stay dark longer.

HMMMM—HUM

Some of the inexpensive receivers have a little too much hum in the audio. This might be lack of filter in the power supply, so the first and most logical thing to try is another 20 μ f. across the power supply. However, usually life isn't that simple, and the next thing to try is to find out if the hum comes from ahead of the audio volume control. If the hum increases with the setting of this control, the hum is coming from somewhere ahead of the control, and this can mean that either the lead from the detector or the detector itself is the culprit. Shielded leads to and from the volume control may be the answer to the problem, at least they're worth a try. If the hum comes in from beyond the volume control, as indicated by no change in hum level with the volume setting, using smaller coupling capacitors between stages will reduce the low frequency response and, consequently, the hum level.

If you're a c.w. man and find that you hear no T9 signals on 21 and 28 Mc., but you do on the lower bands, you have frequency modulation of the high frequency oscillator. This is tough to cure sometimes, but just changing the oscillator tube may help. If the oscillator circuit is one with the cathode tapped "up" on a coil, adding a small low resistance r.f. choke to the ungrounded heater lead may reduce the hum. Don't overlook the possibility of the rough note coming from a humming transformer that vibrates the chassis and modulates the oscillator frequency; the cure here is to tighten the screws that hold the transformer together.

CONCLUSION

A dozen articles might not cover all of the facets of receiver design, test and maintenance, and we claim nothing more than a start for this one. But it will have served its purpose well if a few sufferers of receiverphobia have been started on the road to recovery through the assurance that they have nothing to fear from the receiver itself, the only enemy is one's own ignorance and languor.

² Goodenrich, "Getting the Most Out of Your Receiver," "QST", January, 1954, and reprinted in "A.R." June, 1954.

CORRESPONDENCE

Any opinion expressed under this heading is the individual opinion of the writer and does not necessarily coincide with that of the publishers.

DX COUNTRIES' LIST

Editor "A.R." Dear Sir,

The more I think about this "country" business, the sillier it seems. Of course Hams are recognised as being a little that way to start with, but these different lists of countries for DXCC purposes make things more difficult.

The W.I.A. has its own DXCC but, as far as can be seen, this follows no apparent pattern. One would think that Australia, being a member of the British Commonwealth, would naturally follow the R.S.G.B., but no—the R.S.G.B. countries' list is not a post-war affair. If you worked a fellow back in 1921 you can still get credit for him in the R.S.G.B., but not in the W.I.A.

Seeing then that it is a strictly post-war affair you might think that it would follow the A.R.R.L.—you're wrong again brother. It does not do that either—for instance the A.R.R.L. count the British Phoenix Islands and Canton Island as two separate countries, the W.I.A. says they are not. The A.R.R.L. recognises Aland Islands as a separate country and so does "CQ", but the W.I.A. will not recognise this one, and so on.

The position is further complicated by "CQ" magazine having its own list and discrepancies creep in there also. As A.R.R.L. and "CQ" are both in U.S.A. you would think that perhaps they could achieve uniformity, but again no.

For instance "CQ" recognises the British Virgin Islands as a separate country, but the A.R.R.L. says that this is part of the Leeward Islands, and there are other similar instances.

Why can't we get some uniformity, and if we can't get that, why can't the W.I.A. announce a policy of its own and stick to it—saying that the W.I.A. will compile its own list of countries, then maybe the others would follow and we would get a uniform list.

Let's have a look at the various lists and see how silly it all is.

I can think of nothing sillier than the position in Great Britain where you can get credit for G, GM, GW, GI, GD and GC all in the one island group, under the same Government and using the same series of postage stamps. Here is credit for six different countries. Yet you take the position of Belgian Congo (OQ5), and Ruanda Urundi (OQ0)—separate stamp issuing countries. The A.R.R.L. and the W.I.A. say they are the same place. "CQ" recognises them as different. You will find them as separate in the Atlas.

If Great Britain is to be divided up into six, why can't we divide Italy into three? We already have Italy and Sardinia (I and IS), but although "CQ" recognises Sicily (IT) as separate for country purposes, the A.R.R.L. and the W.I.A. do not. To my mind it is just the same as Great Britain.

There is a dependency of Mauritius called Rodrigues Is, which is a tiny spot some miles away from Mauritius. It has now received country status from the A.R.R.L.—yet Fanning Island and

Christmas Island (VR3), which are just as far apart, are held together as one country. If they split the Caroline Islands into Western and Eastern Carolines, why not this? The same applies to Madagascar and some of the French islands separated from the main island by only a few hundred miles. Because an active Ham is there, it's called a separate country.

No doubt you have heard of Finland and Finnish Karelia (OH and UN). Karelia was the slice of Finland which Russia took. It is now recognised by all as a separate country. Let's have a look at post-war Germany. It is not Western Germany and East Germany in the same position? The Russians took East Germany. It has a separate Government, issues its own stamps and is cut off from Western Germany by the so called "Iron Curtain". I therefore suggest that DL and DM should be recognised as separate countries.

There is also the question of the Falkland Islands Dependencies and the operation therein of Argentine and Chilean Hams. A.R.R.L. and "CQ" recognise a contact with one of these stations as credit for that particular country. The W.I.A. will not, taking the attitude that these stations are improperly operating on British territory and are not therefore properly licensed inasmuch as they were not licensed by the Falklands authorities.

However, I understand that in the International Geophysical Year, foreign countries have permission to operate observation stations in the territories of other powers. Can it be that contacts with "LU" and "CE" stations operating in the Falkland Islands Dependencies during the I.G.Y. will therefore be recognised?

If Arabia is divided up into Aden proper, the Sultanate, Quatar, and Trucial Oman, and Great Britain is divided into its six separate countries, let's have a crack at the assorted States which make up the Federal States of Malaya. Each has its own Sultan and each issues its own postage stamps. Their claims to be considered separate countries are stronger than Scotland and Wales.

Then there is East and West Pakistan—separated by India—surely this is analogous to the Eastern and Western Carolines.

What about New Guinea and New Britain being separated—they are just as much separate countries as England and Wales are—perhaps more so.

If the islands around Madagascar can achieve country status, why can't the islands around Papua New Guinea receive the same treatment?

Perhaps the Americans might grumble if we counted the Aleutian Islands as separate from Alaska—but look at them on the map—they run right up to the Asian mainland—yet the one next to Asia counts as Alaska and North America.

Antarctica is another continent which merits some division—many countries claim portion of it as their own territory. Why can't credit be given for contact with stations which operate in that particular territory? The claims of those countries to the territory they say is theirs, seem to have been recognised internationally so why can't the countries list people bring themselves up to date?

I know that the present Manager of the DXCC, and his predecessor, are both well known DX operators, but apparently the compilation of the list is not left in the hands of one man only.

Can readers please be informed just who does run the W.I.A. DXCC Countries List and what experience (if any) have the people concerned in such matters as Geography, World Affairs, and DX operating?"

There are so many other examples that if I were to quote them all I'd never get this published. However, can something be done about it please?

—Alan G. Brown, VK3CX.

(Federal Executive of the W.I.A. were asked to comment on the above letter. Herewith is their reply: Ed.)

FEDERAL EXECUTIVE'S COMMENTS

Federal Executive has long been aware of the inconsistencies mentioned in this letter. As a result, late last year, the following motion was submitted for consideration by members of the International Amateur Radio Union.

The motion moved by the Wireless Institute of Australia is:—

"That an official I.A.R.U. DX Countries' List be prepared by a committee consisting of a representative from Region 1 (American Radio Relay League), Region 2 (Radio Society of Great Britain) and Region 3 (Wireless Institute of Australia), and all additions and deletions be made only by a unanimous decision of the three region representatives."

Results of the voting on this motion will appear later this year.

—Federal Executive.

OBLIQUE STROKE F.O.C.

Editor "A.R." Dear Sir,

Reference "Oblique Stroke F.O.C. in Feb. issue "A.R." On reading this conglomeration of garbage, my first reaction was to ignore it and treat it with the contempt it deserves, but for the benefit of all concerned I shall endeavour to enlighten readers as to why the "F.O.C." functions.

F.O.C. stands for "First Class Operators' Club". Some of the rules are as follows: "Its aim will be to foster and encourage a high standard of operating ability and behaviour on all Amateur Bands. Membership be limited to those who can send and receive Morse at not less than 18 w.p.m. Can QSY if necessary, break-in single channel working with v.f.o. is desired but not obligatory. Members prepared over the air to assist and advise newcomers to Amateur Radio. Operators will be elected to membership on recommendation of at least five sponsors who they themselves already are F.O.C. members. These sponsors must have been in contact with the operators concerned over the air and be satisfied that he or she can fulfill the foregoing conditions. Members should sign F.O.C. after their call sign. Members of club will adhere strictly to band planning and also members are reminded that good manners over the air are part of first class operating."

What is "snob value, discredit to the true democratic spirit, un-Australian,

un-democratic, time wasting," etc., about the above standards, Roth Jones? There are approx. 181 members in Great Britain and approx. 145 members overseas. On looking very carefully through the P.M.G. Handbook of rules for Amateur Operators, I can see nothing that the signing of F.O.C. after one's call sign commits any breach of the regulations, so I am at a loss to know why Roth Jones thinks it quite illegal.

Soliciting for sponsorship to club is definitely barred and anyone indulging in such practices would have little or no chance of ever becoming a member. Could anyone listen to the excellent operating ability and highly skilful technique employed in transmissions from VK3's FH, RJ, CX, VK4YP, VK-5BY and other members who have been appointed without solicitation and it may be significant that Roth Jones VK3BG has not been invited.

First thoughts, his expressions may be "sour grapes", but perhaps it may well be that he does not measure up to required standards.

Now, concerning the use of CQ/F.O.C. certainly this is used during the Annual Contest between members, how else would they be identified in their own contest?

There is no suggestion of "snob value" in the signing of F.O.C. but rather it should inspire other aspirants to improve their operating ability with a view of future membership. Readers will therefore agree that it is not "un-Australian, un-democratic, time wasting" as stated by Roth Jones, but rather it is an honour to belong to such an International Body of Gentlemen Operators.

Roth Jones' statement re lowering of one's self to be a member of such a clique, is rather in reverse, as no doubt, old timers such as VK3RJ, VK4YP and I include myself will agree that the invitation to join F.O.C. and the day we were duly appointed members was the culmination of more than 20 years of harning.

Roth Jones' reference to "scab labour" and the "plague" brings discredit to no one but himself, as the prestige of membership of F.O.C. remains unaltered and unscathed.

You should know better Roth Jones.
—Roy Baxter, VK4FJ.

[Letters along similar lines have been received from Messrs. E. J. R. Cowles VK6EJ, R. E. Jones VK3RJ, A. L. Klissick VK3KB, and A. Brown VK-3CX, but space does not permit publication.—Ed.]

TECHNICAL CORRESPONDENCE

S.S.B.

Editor "A.R.", Dear Sir,

Once again another is trying to convince himself and others that the trend towards s.b. is not all as is claimed by its users. Article by VK3ACA, February, 1955.

I would like to point out that the British Post Office has spent several thousand pounds on s.b. radio telephone installations, and whether he likes it or not, as a taxpayer he has contributed to several Government installations in this country, that I am aware of.

When I first took up this mode of operation, I was told by another Amateur that s.b. was a passing fancy, and would not last. I note he has purchased and is now operating a complete s.b. station.

It is not difficult to make s.b. sound like an a.m. signal, and the quality can be designed to be better than the average country b.c. station is able to provide to the public. It is also possible to receive s.b. with little strain on a regenerative detector as many s.w.f.s. are doing. It has been proved consistently that s.b. provides a more stable signal, which under given conditions is easier to follow than a.m. signals. The outright statement that c.w. still has the edge on all these systems is open to debate. I have operated c.w. both commercially and for some time on the Ham bands, and was of the same opinion. However, after changing to s.b. Nov. '56, I have conducted tests and each time received better "S" reports for s.b. I attribute this to the frequency diversity effect of s.b., which has the "edge" on c.w. as far as selective fading is concerned. With s.b., the user is concerned with translating the audio spectrum to be used directly to a radio frequency to enable propagation; and the reverse frequency conversion from r.f. to a.f. should take place at the receiver. The use of a product detector or converter does help with the noise problem, because, operating correctly, it is insensitive to amplitude disturbances.

I would like to include the following table for consideration for pure tone signal modulating a.m.—

% Mod.	% Total Power in Carrier	% Total Power in Sidebands
25	100	0
50	87	13
75	68	32
100	56.6	43.3

i.e. one sideband, which is all that is useful with a.m., has only 16.65%.

With s.b., no modulation, no power; 100% modulation is 100% useful signal on the air (like c.w.).

I would recommend that VK3ACA take a trip to some of the s.b. gang in Melbourne and see the system in use.

—V. J. Kitey, VK6VK, s.b.

PEAK POWER FOR S.S.B.

Editor "A.R.", Dear Sir,

I am afraid John Adcock, VK3ACA, in his article in "A.R." for February has made a major error.

In his summing up, para. 7, he says we are allowed a peak power of 100 watts. As an a.m. 100 watt transmitter 100% modulated by a sine wave runs 400 watts peak power, it is only fair to allow this same peak power for the s.b. transmitter.

An a.m. transmitter of 100 watts peak power would have a carrier power of 25 watts and a carrier power of 25 watts is certainly not our power limit.

The comparison of a s.b. transmitter of 100 watts peak power against an a.m. transmitter of 400 watts peak power by VK3ACA certainly illustrates the effectiveness of s.b.

Anyway, the proof of the pudding is in the eating thereof.

—Barry White, VK2AAB.

AVAILABLE FROM STOCK GELOSO VFO'S



Model 4/101 and Model 4/102 with calibrated dial and handsome perspex escutcheon—

£10/4/9

TRANSMITTER CASE with chassis and panel to suit Geloso 28/9/56

★ GELOSO PI-COUPERS

As a companion to the Geloso VFO using the same manufacturer offers a band-switched PI-Coupler with a tuning range of 3.5 Mc. to 28 Mc. of small dimensions and having the capacity of 807 or 6146 output into a load of 40 to 1,000 ohms. Wound on high quality ceramic former—

PRICE 3/16

★ "WODEN" MODULATION TRANSFORMERS

UM1 30 watts Audio, 120 Ma. max. current £17/9/9
UM2 60 watts Audio, 200 Ma. max. current £10/13/3
UM3 120 watts Audio, 250 Ma. max. current £12/2/6

Woden Modulation Transformers will match any set of impedance conditions. Also suitable as output transformers for high quality public address equipment.

★ BELLING & LEE CO-AX CABLE CONNECTORS

Chassis Female Connector 3/6
Cable Male Connector 3/6
Cable Coupling for Joining two Female Connectors 3/6

★
Please include Freight and Exchange with Orders.

**WILLIAM WILLS
& CO. PTY. LTD.**

The House of Quality Products
428 BOURKE ST., MELB'NE
Phone: MU 2426

10,000 TIMES FASTER THAN A SATELLITE

Sydney to Melbourne in two minutes:
this example of the speed of the earth satellite
probably inspires more in us than stating the average
as 18,000 miles per hour.

Sydney to Melbourne in one seven-thirtieths of a
second: this is the speed five thousand times greater
than that of an earth satellite at which electrons
from the Radiotron picture tube gun strike
the phosphor coating on the face of the tube.

As each electron strikes the screen at this
 terrific speed, a flash of light is produced.
By controlling the distribution and intensity of
these flashes the electron gun creates
your television images.

The electron gun is one of the many units that
go to make up the Radiotron picture tube.
Amalgamated Wireless Valve Company introduced
and was the first to manufacture in Australia the
electrostatic-focus electron gun illustrated below.

The electrostatic-focus gun is acknowledged
to give clearer, sharper pictures than earlier
types and to stay in focus under all conditions
of transportation, installation and operation.

It is this policy of using the latest and finest
technique that secures you of the very best
when you buy Radiotron.



RADIOTRON

THE PICTURE
OF QUALITY



AMALGAMATED WIRELESS VALVE COMPANY PTY. LTD. 15 TORR STREET SYDNEY

QSL CARDS

BY E. W. TREBILCOCK,* BERS195

During my 30 odd years' association with Amateur Radio, the humble QSL card has always fascinated me, for reasons more than one. The most important of which is the fact that it is a confirmation in writing of a contact made or a report received. (I am a firm believer in the long established line of thought and action, by a majority, that all initial contacts on a particular band, using a particular mode of emission, are worthy of a QSL card.)

To me a QSL card is more than a mere piece of "wallpaper". (I don't think the term "wallpaper" does justice to a QSL card, anyway.) A QSL card is a picture, portraying the thoughts of man and woman in layout, wording and color schemes. It is an aid to acquiring of world-wide geography knowledge and its passage from point to point provides many a philatelist, such as my son and myself, with an assortment of postage stamps, many of which would be hard to obtain locally. Above all things, a QSL card helps to set the seal of friendship established between peoples of various races, colors, and creeds in some 260 odd countries of the world.

As an added interest, I recently made a careful analysis of just how well (or otherwise) a QSL card is "filled in" with detail by the station operator concerned. I used my inward stockpile for June (90 QSL cards) plus the first 10 QSL cards received for July of 1957, and from the data available I obtained the following interesting results:—

- 95 of the QSL cards bore my call sign.
- 78 were dated.
- 74 mentioned the input power used.
- 73 gave the type of aerial.
- 72 listed the type of receiver.
- 71 mentioned the frequency band.
- 60 quoted the time of the logging.
- 54 indicated the mode of emission (c.w. or phone).

Looking at the results obtained, it is obvious to me that far too many operators spoil their good intentions when QSL-ing, by omitting to include some (or all) of the eight details listed in the previous paragraph. Three facts amazed me, viz:—

- 5 of the QSLs did not include my call sign.
- 2 of the QSLs omitted 7 of the 8 details listed above.
- 48 of the QSLs did not contain an indication whether the QSL was for a c.w. or phone report.

It is my considered opinion that five of the details listed above are a "must" insofar as filling out the QSL card is concerned. The five in question are as follows: Call sign, date, time, frequency and mode. I venture to suggest that any QSL card which lacks any one, or more, of the five "musts" is not a QSL card at all, and is therefore worthless to the recipient. The cards are especially worthless from the point of view of those who claim the many and var-

The VK2 North Coast and Tablelands Zone will be holding its Ninth Annual Convention at Urunga during the coming Easter week-end and all Amateurs, associates, XYLs, friends, etc., are cordially invited to join us for a very pleasant week-end. To defray expenses a registration fee of 15/- for gents, and 2/6 for ladies will be collected.

Accommodation is available upon direct application, or to Mr. Brian Clarke, VK2ZCQ, of P.O. Box 8, Bel-lingen, and I would advise you to book early to avoid disappointment. For the information of the "regulars" the Pilot Guest House has closed down. The available accommodation is as follows:

- (1) Ocean View Hotel, Urunga, approx. 37/6 per day or £11/11/- p.w.
- (2) Guest House, Mrs. Lee, Bonville St. 30/- day or £8/8/- p.w.
- (3) Flats from £8/8/- to £16/16/-, depending on size.

A deposit of £1 per person is required for the Hotel and Guest House, but it is variable for the flats.

The tentative programme is as follows:

Friday, April 4—

- 8 p.m.—General get-together to discuss W.J.A. affairs or similar topics

Saturday, April 5—

- 10 a.m.—Registration and ragchew.
- 3-5 p.m.—Gerry Challender Remembrance Contest on 7 Mc. for portable or mobile equipment—non-mains powered.
- 3-5 p.m.—Heats 144 Mc. Blindfold Tx Hunt.
- 7.15 p.m.—144 Mc. Fox Hunt.
- 8 p.m.—Social evening. 18 watts and perhaps an outline of W.I.C.-E.N. activities, films.

Sunday, April 6—

- 10 a.m.—144 Mc. Transmitter Hunt.
- 11.0 a.m.—VK2WI broadcast.
- 11.30 a.m.—144 Mc. Tx Hunt.
- 3-4 p.m.—All-band Scramble.
- 3-6 p.m.—Heats and finals 144 Mc. Blindfold Hunt.
- 8.0 p.m.—Prize-Giving Concert and films.
- 10.30 p.m.—Disposals Auction, supper and ragchew.

Transport to Urunga is by road or rail, and by air, via Coffs Harbour.

ied world-wide certificates of merit now available to tx men and s.w.l.s alike.

I suggest that all who read this article, and who have time on their hands, select 100 of their most recent inward QSL cards, analyse same along the same lines as I have done, and see how your results compare with mine.

When filling in your own QSL cards for dispatch to the other fellow, give positive thought to completing those eight details (especially the five "musts") I have so often mentioned in this article, and so make your QSL card one worthy of all it represents and a credit to the man (or woman) concerned.

CONVENTION AT URUNGA

The road to Urunga from Sydney is now sealed except for a maximum of 16 miles, which can now be completed by Easter. If you desire to come by plane, please advise the writer in ample time to arrange transport between Coffs and Urunga.

I look forward to seeing a bumper crowd.

—N. A. Hanson, VK2AIH, West Kempsey.

W.I.C.E.N. NOTES

Arrangements are now well in hand for printing Authorisation Cards. Cards will be issued by Federal Executive through the agency of your Divisional W.I.C.E.N. Coordinator. Hence if you wish to be in the first distribution now is the time to register. Obtain full details from your Divisional Coordinator and make sure you fully appreciate the obligations imposed by membership of W.I.C.E.N.

Reports being received from all Divisions indicate a very gratifying interest in W.I.C.E.N. and indicate possible increase in I.Q.T. activities.

During the year interesting and meaningful tests will be arranged for W.I.C.E.N. networks. Reports received from all Divisions are advised to index these notes for ready reference. Apart from continuing publication of our own reports, details regarding overseas activities bearing on subjects of interest to us will be included.

Operating Procedure continues.—

- 11 When a station is called, but uncertain of the identity of the calling station, it shall reply immediately by transmitting: "This is . . ." (giving its own call sign). Say again, please, call sign.
- 12 The responsibility of establishing communication shall normally rest with the radio station having the right to transmit.
- 13 Stations should make use of relay by another station, if unable to contact control direct. Stations should at all times be ready to act as a relay centre.
- 14 When a control station is called simultaneously by several stations, the control station shall decide the order in which such stations shall communicate.
- 15 Should it become necessary to suspend work, because of repairs or adjustments of apparatus, a station shall, if possible, inform the control station beforehand, followed by the time at which it is expected that communication will be resumed.
- 16 When transmission is again possible the station shall so inform the control station.
- 17 When a station is unable to establish communication due to receiver failure, it shall transmit its traffic preceded by the phrase "I am transmitting blind".
- 18 Messages should be transmitted at dictation speed, and the operator may write the message as he transmits it.
- 19 Each station shall listen to all communications on its network, and shall be responsible for rendering communications assistance to other stations as required, provision being first obtained from the control station.
- 20 Each written message shall be read prior to commencement of transmission in order to eliminate unnecessary delays in communications.
- 21 Transmissions shall be conducted concisely in a normal conversational tone; full use shall be made of standard phraseology as prescribed.
- 22 The Phonetic Alphabet shall be that recommended by N.A.T.O.
- 23 The pronunciation of numerals shall be as follows: 1—ONE, 2—TWO, 3—THREE, 4—FOUR, 5—FIVE, 6—SIX, 7—SEVEN, 8—EIGHT, 9—NINE, 0—ZERO.

SILENT KEY

It is with deep regret that we record the passing of:—

Jack Groves, 20/12/57, Member Victorian Division.

* 348 Gilles St., Thornbury, N.I.V. Vic.

BOOK REVIEW

U.H.F. TUBES FOR COMMUNICATION & MEASURING EQUIPMENT

By Members of Philips Electron Tube Division

With use of the u.h.f. bands increasing every day, all Amateurs should be conversant with the latest technique in use on these frequencies.

This book covers a representative range of tubes, circuits and layouts to suit operation in the 300 to 10,000 megacycle spectrum. Both transmitting and receiving tubes are included, the latter receiving thorough attention with a discussion on grounded grid r.f. circuits and standard noise sources. Transmitting tube data covers disc-seal triodes, reflex-klystrons and u.h.f. triodes of standard construction.

Definitely a book recommended to all Amateurs interested in 288 and above.

Our copy from Messrs. Philips Electrical Industries Pty. Ltd., Philips House, 69-73 Clarence Street, Sydney. Price in Australia, 13/-.

TUBES FOR COMPUTERS

By Members of Philips Electron Tube Division

The electronic tube, in its function of an inertialess switch, is one of the essential parts of an electronic computer. The tubes described in this book are specially designed for this use.

As well as comprehensive data on each of the tubes, many typical circuits are published. The data is divided into two sections, one for high speed computers up to the rate of one million units a second, and the other for lower speed computers. A chapter on constructional practice is included.

This book is recommended as a companion to "Analysis of Bistable Multi-vibrator Operation".

Our copy from Messrs. Philips Electrical Industries Pty. Ltd., Philips House, 69-73 Clarence Street, Sydney. Price in Australia, 13/-.

TUBE SELECTION GUIDE

Compiled by Th. J. Kroes

This handy book enables the user of electronic tubes to quickly determine preferred tube types.

A number of tables are included, grouping the tubes according to their most important electrical properties.

The book is most comprehensive in its coverage, and includes data on receiving, transmitting, microwave, industrial, and cathode ray tubes.

Our copy from Messrs. Philips Electrical Industries Pty. Ltd., Philips House, 69-73 Clarence Street, Sydney. Price in Australia, 13/-.

YL CORNER

ELECTRONIC FANTASY

Once upon a time there was a city slicker, the image of a pirate, a genuine parasitic element, a dud who had gone soft. He stole a frequency, he stole a station, and then he stole the band. He also tried to steal tower and antennas. He was after plate and crystal as he used lines of force to blow up the front end and break-in to kilocycle hobbyist. Kilo-watt? Well to kill a radio ham whose junk box was full of such things. The ham became a resistor and strongly impeded the city slicker with a positive charge. Both became heated, the ham made a number of turns and coiled himself up to try to get out of the city slicker's range. The city slicker was a type-free from restrictions and left his mark 2 after using a high voltage probe, whereupon the resistor became a bleeder, but fortunately it was only skin effect.

It was then a case of up and atom and sparks flew in all directions. The ham stung the city slicker with an iron core, deflecting him from his normal path. The city slicker tried to choke the resistor who then neutralised him with a by-pass from a bottle. He felt his pulse which was at zero beat, but he didn't have enough energy to discharge this dummy load as his useful power was now negligible. The city slicker, who was an all-round-looker, then revived and the ham had to stand up to another battery of charges.

The city slicker couldn't get a bearing so he jumped the air gap, hopped on a grounded grid and went for more grid drive, then cycled across the earth to a ground plane and with a coil sign and a way he cut-off making a thermionic emission with a space charge.

The ham finished up with a sore tooth and in addition to losing a megacycle he also lost sink and lost the band.

VALVE DATA

6CB6

SHARP CUT-OFF PENTODE

The Radiotron 6CB6 is a sharp cut-off pentode of the miniature type designed for use as an intermediate frequency amplifier at frequencies up to about 45 Mc. and as an r.f. amplifier in the v.h.f. television tuners.

The valve features a very high transconductance (6,200 μ mhos) combined with low internal electrode capacitance values, and is provided with separate base pins for grid No. 3 and cathode to permit the use of an unbypassed cathode resistor to minimise the effects of regeneration.

Base: 7-pin miniature.

Socket connections:

Pin 1—Grid No. 1.

Pin 2—Cathode.

Pin 3—Heater.

Pin 4—Heater.

Pin 5—Plate.

Pin 6—Grid No. 2.

Pin 7—Grid No. 3, Internal Shield.

Electrical Data

Heater Voltage .. 6.3 volts
Heater Current .. 0.3 amp.

CLASS A1 AMPLIFIER

Maximum Ratings:

Plate voltage 300 max. volts

Grid No. 2 (screen) voltage 150 volts

Plate dissipation 2.0 max. watts

Grid No. 2 input: (for grid No. 2 voltages up to 150 volts) 0.5 max. watt

Peak heater-cathode voltages:

Heater negative with respect to cathode 200 max. volts

Heater positive with respect to cathode 200*max. volts

* The d.c. component must not exceed 100 volts.

Typical Operation and Characteristics:

Plate voltage 200 volts

Grid No. 3 (suppressor) connected to cathode at socket.

Grid No. 2 voltage 150 volts

Cathode-bias resistor 180 ohms

Plate resistance (approx.) 0.6 megohm

Transconductance 6200 μ mhos

Grid No. 1 bias (approx.) for plate current of 10

mA -8 volts

Plate current 9.5 Ma.

Grid No. 2 current 2.8 Ma.

AMATEUR RADIO SERVICE

A NEW SERVICE TO THE AMATEUR including—

- * Modifications to and the re-building of all types of Surplus Equipment to your own specifications.
- * Service to all types of receiving and transmitting equipment.
- * The construction of Amateur equipment to your own specifications, such equipment includes: Receivers and Transmitters both H.F. and V.H.F., All-Band Converters, V.H.F. Converters, Exciters, Receiver Front-ends (single channel or multi-band), Mobile Transmitters and Receivers or Converters, Modulators, Power Supplies, Frequency Meters, "Q" Multipliers, Pre-selectors, Aerial Couplers, etc. In fact anything you may require in the Amateur field can be made to order.
- * Should you have the materials for that certain project, but do not have the time or are so placed that you are unable to complete the job, drop us a line and we will be pleased to assist.

ALL WORKMANSHIP OF THE HIGHEST GRADE AND GUARANTEED.

For further details write to—

AMATEUR RADIO SERVICE

605 ABERCORN ST., ALBURY, N.S.W. Phone: Albury 1695

50 Mc. W.A.S.

Call	Cer. Add. No. Cntr.	Call	Cer. Add. No. Cntr.
VKXWJ	12 4	VKLAZE	10 1
VKXPO	9 3	VKXNA	11 1
VKXVW	9 3	VKXGM	12 1
VKXHY	2 2	VKXACL	14 1
VKXHS	2 2	VKXSD	15 1
VKXSLC	1 1	VKXHO	17 1
VKXGOW	3 1	VKXABC	8
VKXBR	2 1	VKXWE	13
VKXBT	7 1		

VE3N is the first station to appear from the new "invasion" of the Pacific Xmas Is.
 CKSAG is active from Easter Is. on 14, 21 and 28 Mc. phone (2JZ).

ACTIVITIES

25 Mc—3AGH ZLIABZ* ?QL ZLIABZ*
7 Mc.—3AB FAEIRJ*, DJZHC, VERAW,
JAIAEA* ?AIN OXEDL* ?QL G. ZCIP*,
2AMP KA1FF* Ian Thomas JAIAEZ B.
Smyth JAIMZ BERS19 DLXT, DUTSV,
GJZJK, G5JU, GSRP, KR6AK, OHZEC, OH-
SRH, OHTNF, OQSRU, SMSBP, UAIBE, UA-
IYN, UA4FE, UAOCN, UMSFP, UCKAD, UF-

KKA, VSIEN, VSIFJ, VSZDF, YOXU
 14 MC. C-W--048 URZKAA, LZIWD, UA-
 KCFE, UPOLF, 3V8AB, TIEVA, VFRAC
 CNMFX, UASKRA, OKIKTI, UPRBRA,
 UNIAE, UBSKAW, UBRKAE, SACK LA
 2TF, PZ, ZCZAC, VQAS, HASAM/ZA, H-
 6AI, RVICN, SAOH 5V0WH, CRSAI, EA-
 9BN, FBKCK, PICE, UNIAN, LZIKSE,
 ILIDW, ZKAC, HSIC, ZEBZ, VSJAJ, UA
 KDDW, CNZBE, 048, UBSKA, MF-
 4BBL, UANBN, KMBG, ITITAI, ISFIC,
 LJJD, VREN, EABCE, FKAD, EASAU, 6K-
 TAK, OVYMI, ELASAC, FBCE, HCBRE, UR

1AT, HLKKS, IAIK, CT3AB*, KP4AZ*, JT-
1AA*, CR8AC*, XE1BY*, XWBAX*, HS1C*,
VK0KT*, ZC5RF*, UL7HB*, SV0KS*, V88AJ*,
E13AC*, HCUJW*, KC4USA*, ZC3AB*, XW

Frank T. Hine, VK2QL
29 Abbotsford Road,
Hornsby, N.S.W.

Am now back again to all the "chores" after a delightful holiday in Adelaide, and strange as it may seem there was not much talk of DX when with any of the VK5 boys I had the pleasure of visiting.

Some good DX has been on the bands if you were fortunate enough to be on at the time, but no two days were the same. Some very short skip has been evident at night in Eastern Australia and the DX stations have also been complaining of the short skip in their areas. Many strong W signals have been heard on the long path in the mornings.

Entertainment **WKVU** for a few hours whilst he was in Sydney and he was most interested to be on the air from "down under" and heard that he was the first person to do this. He came out of our talk zone of which is the way the leading DX boys in the States operate. He was a very nice fellow and he said that there is on the band and hears something worthwhile in the line of DX, telephone calls and mail. He said that he had been on the local calls, as they can become coast to coast. **WKVU** has made calls of over 1,000 miles. He said that he had been on the air for instance when he rang a WO asking him to reply but a **VQI** he was working, receiving the reply as a best. He said that he had been on the air for a long time and he knew how the **W** stations appear in profusion when something worthwhile shows up. Most of them were

NEWS AND NOTES

The reference to ZLIABO in last month's notes is to be corrected to ZLIABZ. If you need the Kermadec Is., and who doesn't, ZL-SGX or VKSAD may be able to arrange something for you even cross band. Generally he listens for a.m. only, but can read slow c.w. Power is 100w. and gets out quite well.

Activity from FWSAA has temporarily ceased as he is in hospital at Noumea and will be in Noumea for some time (EACK)

Although it is shown as acceptable to the A.R.R.L., the Asland Is. is not being allowed for Australian DXCC credit (JCY).

There is renewed possibility of activity from the Maldives as there is a change of command taking place, and the new C.O. is an ex-Australian.

BACH overheard on HR station telling a DX station that the HR Bureau was not functioning at present and that many cards had been "lost".

A strange call appearing on the 14 Mc. band is FK0AD. Gave his QTH as Chesterfield Ia. JT1AA is now active on 11 Mc. The first QSLs from this station have arrived in Australia, but were only four in number.

The XYL of JTIAA is on 14 and 21 Mc. with the call of JTIVL.

PYICK/U has been active on 14 Mc. phone, PYICK often acting as the link.

UPOLY is the call of the Russian station in the Amateur bands operating from the North Pole (2EG).

CEZSO has now QRT and returned and is

ZL1ACV is operating from Antares as
ZL3AC and plans operation on all bands.

VKSAD is having difficulty in getting his cards. Soz there are hundreds somewhere for him. He asks that all his cards be routed through the VK2 Bureau and that if a DX

station seeks his QTH, tell him it is Norfolk Island via Australia, as many cards are being returned to the DX station if Norfolk Island only is shown as the address.

XVSA is W3ZA operating from Saigon. He expects to have 1kw. on a.s.b., a.m. and c.w., usual hours of operation being 0100x-0130x and


WWSAA QSLs are reaching him OK via the OK Bureau. Have not heard Phan for some time.

* Call signs and prefixes worked.
 †—zero time—G.M.T.

Does this make you do a bit? It is Dick Kivvas seated in his shack. He has two of everything, drivers, finals, a.s.b. exciters, etc. plus kw ga generator. On the top shelf spare electronic key speakers, ant. couplers Middle HT-32, B and W 518B, Collins 310-B HT-33 amp. Ranger. Table: Audio keying speaker, SX-101, El-bag controls, 75A-J control panel (selects antennae, switches drivers to any final, etc., etc.), Johnson KW The antenna farm consists of a 3 element beam 75 ft. up on Vesto tower for 14 Mc., 3 element beam 40 ft. up on Vesto tower for 14 Mc. most days takes care of 1.5, 3.5 and 5 Mc. It is fairly new and we will hear him on 14 Mc. most days 1630 to 1700 GMT. DX is fine and he has ~~him~~ confirmed tone behind W1FH!.

JAI, KXG*, SVTW*, OQSEH, ZAMB
 KBNQW* VYSG* LUDXJ, CEAD*, CX-
 CO, V58RA, JTJIA*, BSIC*, VKJKT*, ZC-
 3AP, VQSC*, YJLID, FBUCD, PJCC, VSCG
 KGHIL, BKAN, ZCAN, ZCSR*, VQGLQ, ZH-
 OXG*, MPMBR, HASBO*, HASDH*, OH-
 OXG*, OXG, HPC*,
 XWRA*, XVSA* CTJAB, CRAC*, HLAP,
 HJHLD, UGUKAA OQGB, ZPIAP, VS9AJ,
 FLAC*, KZTH*,
 ZCZC*, JTYJ*, FQAP, ZDZDC*, ZD-
 PD, PJBA, HZLAB, HZIV, VQ8AS, APZAD,
 ZCAC*, VKJF, FBEDX, LKXID, VKIAT, UD-
 LK, VQ8AS, VQ8AS, VQ8AS, VQ8AS,
 SLK, UQSC*, UPIXC*, LZIXP*, ITJAI*,
 ITPIDN, CNNEK, CNGCV*, ZSAGY*, CN
 BCJ, VYIAD*, VSVH*, LUNIR*, LUSPRH*,
 VQ8AS, VQ8AS, VQ8AS, VQ8AS,
 ZCAC*, VQ*, LU, VYSG*, ZC4PT*, VQ-
 GLQ, LUNZD*, VQKPB*, VHSB*, BSIC*, LA-
 BEP*, ZCZC*, CRSL*, EFL, UGUKAA,
 UGUKAA, UGUKAA, EFL, UGUKAA,
 UGUKAA*, VQGLQ*, ZCSR*, HCLJY*, SV-
 LK, VYIUS*, XVSA*, VQ8AB, ZCSAL, XW-
 RA*, VQ8AS, VQ8AS, VQ8AS, VQ8AS,
 XGKY*, ULNG, UGUKAA, CRSH, CTBAB

PZJAP, CBSAC, ULTKBA, SAITY, CMHUX
VQKTC, HESLAE, HLRKS, CSSAD, VQSGJ, VQ-
AKRL, HZIVB, VQBCF, VPPPJ, ZJZ, UA
OKPD, UAKAEK, VQ3CF, VQ8AP, SVYWH,
VK9AD, 3GM, VUZED, EASFK, *4JAZ,
UP6L7, UA9KKB, 58K, SMHBY/MNE,
JAZAE, Jan Thomas, KR8DA, KJHES, BRB-
K, PZJAZIA, VQ3CF, VQ3AC, 3GM, KBA-
OQJSE, MP4BBE, OY3M, PY4AO, PHIRS,
SUIUM, U38AG, UH8BA, VUZNA, VOLDX, ZC-
5AB, 3V8AO, 4X4JU

[illegible]

SCD, CNEMM, OA4IGY, MP4KAA, HC1FG XQ-
SAG (see QTH). BEEN105: BV1US, EA3GH,
795RH.

[illegible]

Q8Ls RECEIVED

A large and interesting batch of Q8Ls have been received by the VK2 gang during January, with increased confirmations for DXCC

4AB VIRC, 3ACK HVICN, 5V0WH, Z87C,
7WAA 1, 3AGH 7S19, UAAE, UAAKCE, CR-
EAC, Z04F, 7YAA 5USCW, W6UCU/KSE
7WAA 5V0WR, TGRAD, 2AB W4FCB/K5A,
H23CL, UDXKAB, UP2AT, UAQOM, UIRAN,
7TBA, VP6CW 2AMS VK0AB 7 and 24

Me's, HKTAIR CN80GL, LITERAJ, FKWTW, FY-
TYF, PARCF, SP8KBE, FB8ZZ, EAPBK, EA-
SCC, HC1HL, UNBUW, LASQ 30W 3VBAA,
VAIKAE, RQJ, ZB1CB, HASEB, ZJ2CC, DE-
PKAA, BV, US, UC2CB, HAQOM, UQ2KAA,
4X4DR, 4X4BX 984CB, ZS3AG, ZS3Q, WUOU/
K56, KPA1, FB8AS, VA1KAE, ULTHR, BQ-
JAG, UMEKAA, BE881B, CRAC, 884DW,
HRLH, KZ5RF, PY1BF, CA4SF, UHSWD,
ZDRM, EM8BC/MM

QTH OF POSSIBLE INTEREST

HS1C—Box 189, Bangkok.
VP8CW—QSL via ISWL.
VR5A Box 2 Tonga 3CX.
HZ1VB Box 167, Jeddah Saud, Arabia 4DO1
BQ1C1 University College Accra Ghana
(4XJ)
XQRAG—No. 7 Vanguard Station, C/o U.S.A.
Consulate, Antofagasta, Chile
ISFL—Box 90, Mogadishu.

Before I finally wind up the rest and put out
the clock, Hans JAHH has asked me to pass
on his 73 to all VK DXers. He may return
from his days there was a Xmas card and
letter waiting for me. Hans gave no indication
when he may be back, but as he holds a
superior post in the IGY organisation on
Ionospheric research, which is keeping him
on the move throughout Europe, I should say
that we won't see him until the end of the
IGY task, although he hopes he may be on
with something QRP in his travels. He is not
out of touch completely as he gets his copy
of "A.R." although almost three months old.

And so my thanks to the following, some of
which is welcome "new blood" QSO for his
regular QRP of 8AB whilst Chas has been at
M. Woon, JACK who now has the fine total of
262 worked. JAGH torn between trying to
watch the hands for the good ones and build
a new tv. JAH is wondering when conditions
will stabilize back home. Alan, ZAMB still
able to dig out the occasional good one and
played with the QSLs he is getting. EJE who
is trying a QSO on 21 DC and we welcome
his first contribution 30W waiting on three
QSLs to confirm his W.A.S. EER added two
new ones for the month. NCK who is happy
with his cross-band with ZLIABZ 400 who
is having some QRI trouble, 4XJ who manages
to score up something satisfactory on 28 Mc.
HAOM whom we hope to see regularly listed
on the page 8HK for his QRP of 8GM and
SWP. BERRIS has now reached a total of
235 confirmations. Barney Smyth is interested
in a serial, and finally we welcome to the page
Ian Thomas of Clayton VKZ.

D.X.C.C. LISTING

Listed below are the highest twelve
members in each section. New members
and those whose totals have been
amended will also be shown.

PHONE

Call	Cor. Cnt- No. ries	Call	Cor. Cnt- No. ries
VK3ATN	26 204	VK8DB	31 161
VK4FJ	21 202	VK4WF	16 160
VK4HR	12 192	VK4RW	23 157
VK6RU	2 191	VK3JD	1 153
VK3BZ	3 176	VK4KS	9 152
VK3EE	10 163	VK6RW	4 150

Amendments

VK4DO 20 123

C.W.

Call	Cor. Cnt- No. ries	Call	Cor. Cnt- No. ries
VK4FJ	29 234	VK3KU	48 213
VK3FH	15 234	VK3BY	45 202
VK3BE	10 228	VK3DO	2 191
VK3CX	28 222	VK3YL	30 190
VK3BZ	6 222	VK3RS	18 178
VK4HR	8 218	VK6RX	23 176

Amendments

VK4DO 20 123 VK4RW 47 165

New Members

VK4IR 80 102

OPEN

Call	Cor. Cnt- No. ries	Call	Cor. Cnt- No. ries
VK2ACK	6 229	VK3JE	12 210
VK4FJ	32 234	VK3B	69 210
VK4HR	7 233	VK3HG	3 201
VK3BZ	4 231	VK3NS	16 195
VK6RU	8 221	VK3DB	90 182
VK3KU	61 221	VK4RW	82 179

Amendments

VK4DO 15 173 VK4WF 40 165

PREDICTIONS FOR MARCH, 1958

Me. E. AUSTRALIA — W EUROPE S.E. Me.

45	0	2	4	6	8	10	12	14	16	18	20	22	24	45
29														29
21														21
14														14
7														7

E. AUSTRALIA — W EUROPE L.R.

45	0	2	4	6	8	10	12	14	16	18	20	22	24	45
29														29
21														21
14														14
7														7

E. AUSTRALIA — MEDITERRANEAN

45	0	2	4	6	8	10	12	14	16	18	20	22	24	45
29														29
21														21
14														14
7														7

E. AUSTRALIA — N.W. U.S.A.

45	0	2	4	6	8	10	12	14	16	18	20	22	24	45
29														29
21														21
14														14
7														7

E. AUSTRALIA — N.E. U.S.A. S.R.

45	0	2	4	6	8	10	12	14	16	18	20	22	24	45
29														29
21														21
14														14
7														7

E. AUSTRALIA — N.E. U.S.A. L.R.

45	0	2	4	6	8	10	12	14	16	18	20	22	24	45
29														29
21														21
14														14
7														7

E. AUSTRALIA — CENTRAL AMERICA

45	0	2	4	6	8	10	12	14	16	18	20	22	24	45
29														29
21														21
14														14
7														7

E. AUSTRALIA — E. AFRICA

45	0	2	4	6	8	10	12	14	16	18	20	22	24	45
29														29
21														21
14														14
7														7

E. AUSTRALIA — FAR EAST

45	0	2	4	6	8	10	12	14	16	18	20	22	24	45
29														29
21														21
14														14
7														7

W. AUSTRALIA — W. EUROPE

45	0	2	4	6	8	10	12	14	16	18	20	22	24	45
29														29
21														21
14														14
7														7

W. AUSTRALIA — N.W. U.S.A.

45	0	2	4	6	8	10	12	14	16	18	20	22	24	45
29														29
21														21
14														14
7														7

W. AUSTRALIA — N.E. U.S.A.

45	0	2	4	6	8	10	12	14	16	18	20	22	24	45
29														29
21														21
14														14
7														7

W. AUSTRALIA — S. AFRICA

45	0	2	4	6	8	10	12	14	16	18	20	22	24	45
29														29
21														21
14														14
7														7

W. AUSTRALIA — FAR EAST

45	0	2	4	6	8	10	12	14	16	18	20	22	24	45
29														29
21														21
14														14
7														7

They're all at U.R.D.

Here we show you just a FEW of the
famous brand names available from our
new Warehouse in the Hi-Fidelity, TV,
Electronics and Electrical field.

Orders and enquiries will be given
prompt, courteous attention.

GOODMANS

Technico

permanoid

EDISWAN

Ferrograph

QUAD II

HECLA

M.B.H. Polar

UNITED RADIO DISTRIBUTORS PTY. LTD
175 PHILLIP STREET, SYDNEY. BL 3954. BOX 3456, G.P.O.

THE

Frank P. O'Dwyer, VK3OF
180 Thomas Street,
Hampton, Vic.

Unprecedented events marked the past month's activity on 80 Mc. VK3EF heard K8H, W0 and K0. VK4ZBF swapped calls with K8RQ; VK3-4-5-7 worked into JA; auroral contacts from VK3 to VK3 and 7; K17 heard in VK3. What more is required to set the gang in all States on edge, waiting for the next break-through to who knows where?

Here is the sequence of events from the information to hand. Jan 11, 1900 E.A.S.T. for about 10 mts. VK3EF heard K36UJL on 80.3 Mc. R4 85 with quick futter QSB on the signal, during the same period on 80.23 and 80.24 Mc. a W0 and a K0 were heard in quick QSB conditions but enough of the signals were received to allow confirmation of the prefixes. By 1715 E.A.S.T. the signals had disappeared. VK3EF was using a 4 al. beam 48 ft. high with gamma match to co-ax line feeding into a 55Q7 cascade r.f., 6U9 cas. mixer, 6SN7 cathode follower to 30 meg. i.f. through pre-selector to a 76A3 receiver. Unfortunately no transmitter was on hand to go back to the stations heard. Jan 22 at 1200 E.A.S.T. VK3NR (Storham) contacted JAZZW, the first recorded VK3-JA contact ever.

Feb 3 had two openings, northern VK to JA and southern VK south. JA signals poured into VK4 for several hours and many of the local gang made their first JA contact on 80 Mc. VK4MM was apparently putting an excellent signal into JA going by the dopple which developed on his frequency. That is one feature of JA operating, they vary their v.f.o. onto the station they call. At 1140 VK3 had a short opening to VK3 and while this was in progress VKTAB proceeded to contact JAJAX at 1150. Each was R4 85, to the other though they lost one another in the end after a good contact. With Doug. TAB located

in Hobart it will take a contact with Macquarie Island to give the JAs a longer distance. In the evening VK3 had an opening to VK3 and ZL with an extended opening to VK1. Again here many VK3s made their first VK1 contact. With so many signals coming in from the south, the VK3 beams were swinging madly from ZL to VK3 through VK1 and back again. During this period VK3OF set on one signal (1908 E.A.S.T.) and identified it as VK4AA calling VK3MFC. VK4AA was using a 600 Mc. Macquarie Island (replaced by 0KT) the query now is "was it JABAA off the back of the beam?" Was JABAA one of those worked by the VK3 gang? During this same evening VK5 had an excellent opening to JA, the first ever once again. According to the A.L.C. News service the following morning, Col SRO worked 11 and Reg 3431 contacted 4. Maybe others were in on it too.

Feb 5—Gerry 323N at 2047 E.A.S.T. heard a K1J calling CQ VK1 or JA. A strong local signal made copy difficult at times, the signal also having a sharp scatter futter/ fade on it also. At 2100 on approx 80.1 a similar type of signal appeared for a short period but the rapid QSB made identification impossible.

Feb. 8 at 1045 VK4ZBF listened to a signal which signed KERNQ. Allan called to be answered as VK3ZBF, but after several efforts was correctly identified before the signals went out. It is not known whether signal reports were exchanged by each station, though the calls definitely were. Allan was using a mere 8 watts to a 2 el. cubical quad, his final being a 2B8. Receiver was a 4AK3-438 converter into a 5-6 Mc. Command receiver. Unfortunately while this was going on Allan was the only VK4 on the band. How about going QRO Allan? During this period the ZLs were steadily working across the Pacific to the west coast of W. land. Once again both first, VK/W, ZL/W

Feb. 10 in VK3 at 2145 E.A.S.T. weak signals from the north came up on the band, at 2210, Len 3ALZ raised his first JA. Len went on to work 4 more while the rest of the gang called in frustration to no avail. The first meg. of the band was full of JA signals to ST, but copy was difficult because of the sharp QSB futter coupled with language difficulties. A terrific dog-dile developed on Ray 3ATN (Birchpi) while 32CW (Guyen) appeared to be in the thick of it also. General consensus of

opinion was that it was a "scatter" type of opening.

Feb. 11 provided an anti-climax as well as some amusement for the VK3 gang with an excellent auroral spacing. With VK3-3-5-7, beaming south at the aurora, VKTAB/VK1ZL broke the ice with an intrastate contact, followed by VK1/VK3, VK1/VK4, VK3/VK2, with VK3 calling VK1 though no sign of him in VK3. Signals between VK1/VK3 peaked 9 plus at times allowing phone contacts, but for the most part c.w. was the obvious choice. Signals such as those on the band had to be heard to be believed. All d.c. characteristics were lost, c.w. sounding like a square toothed buzz gone mad. Even strong 59 plus local signals developed the auroral effect, ground waves being conspicuous by their absence. VK1/VK3 contacts were by phone, difficult copy at times, hope the Z call boys are out to get their full tickets, they would get a lot more contacts under auroral or fringe conditions. Col TLZ alerted Len TBQ by landline whilst Doug TAB started off on phone without any method of keying, but promptly rectified that, it did not take him long to pound brass.

SKEDS AND THOSE TO LOOK FOR

VK3KT, Macquarie Island, runs automatic c.w. on 80.18 Mc. beaming north, calling and listening in a sequence of 5 minute periods on Saturdays and Sundays at these times E.A.S.T.: 1800-1820, 1900-1920, 2000-2030, 2100-2130. Up and down the VK east coast various Hams are running skeds with K8H and W around 0700 E.A.S.T. on 81.8 Mc. If you are looking for VK contacts so tune up that far if you can boys, while XE1GB just inside band edge, with high power and a good location is beaming at VK also. With so much interest being displayed overseas in the VK direction and conditions as they are, there should be opportunities for everybody before the band closes up. Of interest is an extract from a letter received from Vern 4LX. From JASOW (Jan. 30) he has worked K17, VZ7, W6, 7, 8 on 80 Mc., all this taking place in the morning from around 8 a.m. to 8 a.m. Jap. C.E.T. (0100-0900 E.A.S.T.). JASW, who does not work (locally), has had over 100 contacts with the west coast of W. land and Canada. Another first overseas was with W10 on 80.23 Mc. on Jan 25, believed to be a single hop contact (1930 G.M.T.).

VK3 appear to be out of all this lack of news to date) but with the activity evident in South

Behind



THIS SYMBOL . . .

**LIES A WEALTH OF EXPERIENCE
IN THE MANUFACTURE OF
UNIFORMLY RELIABLE TRANSFORMERS &
ALLIED TECHNICAL COMPONENTS, ETC.**

Whatever you build you need a foundation. The basic designs and necessary research for TRIMAX Quality Products come from our fully equipped Laboratory with its complete technical library. Our products include POWER TRANSFORMERS air-cooled to 10 KVA, POWER and AUDIO CHOKES, AUDIO TRANSFORMERS of all types, CURRENT TRANSFORMERS, AUDIO and POWER AMPLIFIERS, special high-quality TEST EQUIPMENT, SOLENOIDS, IGNITION TRANSFORMERS, IGNITION COILS, FADERS, GAIN CONTROLS, custom-built SHEET METAL and many other products in these and allied fields.

**OUR RANGE COVERS ALL TYPES AND ENSURES THAT THE
RIGHT TRANSFORMER IS AVAILABLE FOR THE RIGHT JOB!**

TRIMAX TRANSFORMERS PTY. LTD.

**CNR. WILLIAM RD. & CHARLES ST.,
NORTH COBURG, VIC. Phone: FL 1203**

We issue regular details of new Transformers or improved existing types. Register your name and address with us now!

FEDERAL

Fed. President: W. T. S. Mitchell, VK3UM.
Fed. Secretary: L. D. Bowie, VK3DU, Box 3211W, G.P.O., Melbourne, C.I. Vic.

Editors:
New South Wales—Bob Goddall, VK3ARG.
Victoria—Dave Wardlaw, VK3ADW.
Queensland—Arthur Walsh, VK3AAW.
South Australia—Ray Richards, VK3KD.
Western Australia—Ron Hugo, VK3KW.
Tasmania—Doug Fisher, VK3AB.
Fiji—New Guinea—Russ Collins, VK3KX.
Fed. Contest Committee: Reg Harris, VK3HR.
Secretary: Box 1234K, G.P.O., Adelaide, S.A.
QSL Bureau: R. E. Jones, VK3RJ, 23 Landale Street, Box Hill, E.I. Vic.
Awards Manager: A. S. Weynton, VK3XU, 5 York Street, Bonmahoe, Vic.

NEW SOUTH WALES

President: Perc. Healy, VK3AGP.
Secretary: Keith Woodward, VK3ZAU, Box 1734, G.P.O., Sydney.

Meeting Night: Fourth Friday of each month at Science House, Gloucester Street, Sydney.

QSL Bureau: Box 1734, G.P.O., Sydney. Frank Hine, VK3QL, Manager; assisted by Alan Smith, VK3AD.

Zone Correspondents: North Coast and Tablelands—Noel Hanson, VK3AHN, Ryan Ave., West Kempsey, Newcastle; Les Sparks, VK3ACR, 10 Kaituma Rd., Highfield, via Adamstown, Colleys and Lakes; H. Hawkins, VK3ZYL, 2 Comfort Ave., Cessnock, Western; W. Stitt, VK3WV, "Cambridge" Ave., 2211 St. Clair & Southern; E. Fisher, VK3DY, 4 Oxley St., Warrswang; 8th. Western; J. W. S. Edge, VK3JAD, Wallace St., Coolamon; Tamworth: F. Fowler, VK3JFF, & Thompson Cres., Tamworth.

VIETNAM

President: F. G. Ball, VK3Y5.
Secretary: J. R. Lancaster, VK3JL.

FEDERAL

CHANGE OF FEDERAL SECRETARY

Federal Executive is pleased to announce that for the next six months, Mr. Bob Bowie, VK3DU, will be taking over the duties of Federal Secretary of the Institute.

This change is necessitated by the fact that the present Federal Secretary, Doug Bowen, VK3DU, and his XYL are making a world tour in the near future.

Bob is active on bands 40 and 80 metres and can often be heard during the week-ends.

For those wishing to contact Bob, his phone number is PJ 3531 during business hours and PJ 1865 at other times. As usual all mail should be sent to the postal box—No. 3211W, G.P.O., Melbourne.

VKS FEDERAL COUNCILLOR

Word has been received by Federal Executive that the Federal Councillor for 1958 will be Mr. Rex Richards, VK3DU. Rex will be taking over from Mr. Gordon Bowen, VK3DU.

All members will support Executive in saying thanks to Gordon for his fine work during the past year. Through his fine efforts in the Division and by means of the broadcasts over VK3VU, Gordon has been able to maintain contact with members thought and translate them into action. It is his aim to remain conciliatory at the last Convention will be well remembered.

However, VK3 are extremely fortunate to have another very able member to follow in Gordon's footsteps. Rex has had experience in Conventions and then as Manager of the Federal Contest Committee, he has been able to gain an insight into the Federal sphere.

Executive is happy to say a very big "thank you" and an equally big "welcome".

VISIT OF VK3 FEDERAL COUNCILLOR

A welcome visitor in Melbourne during the last couple of months was the VK3 Federal Councillor, Russ Coleston, VK3KXK.

During his visit, Russ was able to have a number of discussions with Federal Executive. As a result various aspects of problems confronting the Institute have been given consideration.

FEDERAL QSL BUREAU

Please note that the complete address of the Greek QSL Bureau and which should figure on all correspondence addressed to 5V Amateur is: QSL Manager George N. Zarlis, Box 264, Athens, Greece.

A new award from Japan styled "The DC-25 Award" and sponsored by the Japan Double

NOTES

Administrative Secretary Mrs. May, C.O.R. House, 191 Queen St., Melbourne.

Meeting Night: First Wednesday of each month at the Radio School, Royal Melbourne Technical College.

Divisional Sub-Editor: V. M. Jones, VK3YE, 7 New St., Surrey Hills, E.Io.

QSL Bureau: Inwards & Outwards—W.I.A., 191 Queen St., Melbourne, C.I. Vic.

Zone Correspondents: Western: W. J. Kinella, VK3AKW, Magdalla, Lubbeck; South Western: W. Wines, 48 Cranley St., Warrnambool, and W. Zimmer, VK3AJW, 10 Skene St., Newtown; Far North Western: M. Felle, VK3QZ, 101 Lemon Ave., Mildura, Mildura; R. Jackson, VK3KD, Farnsworth St., Castlemaine.

North Eastern: L. Elison, VK3ALE, 72 Orr St., Shepparton; Eastern: J. Spark, VK3AJK, 20 Marshall Ave., Moee.

INTERNATIONAL

President: Frank Bond, VK3EM.

Secretary: W. J. Rafter, VK3PE, Box 636J, G.P.O., Brisbane.

Meeting Night: Fourth Friday in each month at the State Service Union Rooms, Elizabeth Street, Brisbane.

Divisional Sub-Editor: A. Simpson, VK3EAR, 37 Baden Powell and White Sts., Everton Park.

QSL Bureau: Inwards—J. Flies, VK3AF, Vanda St., Buranda, Outwards—Miss Clair O'Brien, 23 Jardine St., Stafford.

Call Club is unique and interesting. The certificate may be claimed by any licensed Amateur who submits proof of having worked 25 double or triple call sign stations. Examples: JA1Z, G3CZ, VK3WZ, W3BZ and so on. Contacts must have been made AFTER JULY 30, 1952, and the submission must contain at least five or six stations on either phone or c.w. Send QSL with a check list and 10 L.R.C. to Double Call Club, JA1CC, Akira Asano, 257 Eihuku, Saginami, Tokyo, Japan. The QSLs after check will be returned by registered mail together with the award. The award is also available to a.w.l.e.

The correct address for the India QSL Bureau is: Box 534, New Delhi, India. The old Munrar address must not be used.

Once again the well known Helvets 23 Contest is coming up. The U.K.C. has scheduled it for the following dates: 1500 GMT May 17 to 1700 GMT May 18. The object of the contest is for stations outside HB to work as many stations in each of the 23 Swiss Cantons as possible. All Amateur bands may be used for c.w., e.w., or voice-voice contacts, and the usual serial exchange is to be made. Three points are earned for a contact with any Swiss station on each band. The total points earned on all bands are multiplied by the sum of all Cantons worked on c.w., phone or both together on all bands, hence the maximum multiplier possible per band is 44 (23 c.w., 23 phone). Entries must be submitted on separate sheets for each band and

Zone Correspondents: Maryborough: R. J. Glasson, VK4BG, 88 North St., Maryborough, Tasmanville; R. E. Wilson, VK4RW, Hagart St., Stuart, Townsville.

SOUTH AUSTRALIA

President: W. J. Bulling, VK3KX.

Secretary: B. W. Austin, VK3AD, Box 1234K, G.P.O., Adelaide. Telephone UX 2821.

Meeting Night: Second Tuesday of each month at 17 Wymouth St., Adelaide.

Divisional Sub-Editor: C. Daw, VK3EF, P.O. Box 44, Gawler, S.A.

QSL Bureau: G. Lutzon, VK3RK, 31 Belair Rd., West Melbourne, C.I. Vic. (Outwards)

WESTERN AUSTRALIA

President: J. K. Rumble, VK3RU.

Secretary: J. R. Elms, VK3RE, Box N1003, G.P.O., Perth.

Meeting Night: Third Wednesday of month at Perth Tech College Annex, Mounts Bay Road. Divisional Sub-Editor: E. J. R. Cowles, VK3EF, P.O. Box 11, Benger, W.A.

QSL Bureau: Jim Rumble, VK3RU, Box F318, G.P.O., Perth, W.A. (Inwards and Outwards).

TASMANIA

President: F. J. Evans, VK3Y7.

Secretary: M. Hurburn, VK3MH, Box 311B, G.P.O., Hobart.

Meeting Night: First Wednesday of each month at V.I.A. Clubroom, Liverpool St., Hobart.

Divisional Sub-Editor: W. W. Watson, VK3YV, 38 Brookier Ave., Moonah.

QSL Bureau: K. A. Johnston, VK7RX, 34 Tower View, Wynyard.

Zone Correspondents: North: K. J. Briggs, VK7LX, 15 Melbourne St., Launceston; North S. E. Edgington, VK7LS, 3 Jenner St., Wynyard.

PAPUA—NEW GUINEA

President: F. N. Nolan, VK3FN.

Secretary: N. T. Casey, VK3NT, Box 204, Port Moresby.

Divisional Sub-Editor: R. Clark, P.O. Box 301, Port Moresby.

QSL Bureau: R. Lloyd, VK3ZAL, Box 304, Port Moresby.

—Ray Jones, VK3RJ, Manager.

FEDERAL AWARDS

W.A.V.K.C.A.

VE3VW, W3ARA and G3KS have been issued with W.A.V.K.C.A. Certificates. The total number of certificates to date is 71 only.

—Gordon Weynton, VK3XW, Manager.

NEW SOUTH WALES

On Friday, 24th January, members who attended the monthly meeting of the N.S.W. Division had a very interesting evening. A. J. L. Stevens, VK3ZS, was the guest speaker with Mr. Max Hull, VK3ZS, our Federal Vice-President, was the order of the evening.

Mr. Stevenson lectured on transistors and various applications in which they could be used. By the use of slides the various methods of using transistors were described and comparisons made with similar circuits using conventional type valves. Several types of transistors which are not yet available in Australia were also described. At the conclusion of the lecture many questions were asked by members and Mr. Stevenson very capably answered. A hearty vote of thanks was moved by Bill EXT. who then drove down Newcastle to attend the Convention at Dural.

The Chairman introduced Mr. Max Hull, VK3ZS, to members. Max then spoke on various phases of Federal Executive's work in Institute affairs. Many points on the magazine "Amateur Radio" were discussed and several suggestions made by members were noted by Max who assured them that he would refer them to the Magazine Committee on his return.

Federation of the Institute was also mentioned but suggestions that some of the problems would have to be solved, it should receive due consideration as it was conceivably that many advantages would be gained.

The necessity for the Amateur of Australia to be represented at the International Telecommunication Union Conference at Geneva

CONTEST CALENDAR

Compiled by W.I.A. Fed. Contest Com.



A.R.E.L. DX COMPETITION

Dates: Phone—March 7 to 9; C.W.—March 21 to 23.

Times: 2400 hours (7th, 21st) to 2400 hours (8th, 23rd).

Cypher: RST followed by power input e.g. RST 589075 for c.w., 57100 for phone.

Scoring: "QST", January, 1958.

REMEMBER DAY CONTEST

Dates: Saturday, 18th August, 1958 hrs. E.A.S.T.; Saturday, 17th Aug. 1958 hrs. E.S.T.

Rules: See amendments, February issue.

Voting returns date: 31st March, 1958.

1958 EDITION

RADIO AMATEUR'S HANDBOOK

PUBLISHED BY AMERICAN RADIO RELAY LEAGUE

WILL BE AVAILABLE FOR DISTRIBUTION DURING MARCH, 1958

Price 46/3 and 2/- Postage

This edition will maintain the same high standard as has previous editions.

BOOK YOUR ORDER NOW

McGILL'S AUTHORISED NEWSAGENCY

Est. 1860

183-185 ELIZABETH STREET, MELBOURNE, C.1, VICTORIA

"The Post Office is opposite"

Phones: MY 1475-6-7

BRIGHT STAR RADIO

46 EASTGATE ST., OAKLEIGH, S.E.12 UM 3387

AMATEUR PRESSURE-TYPE CRYSTALS

3.5 and 7 Mc. in FT243 type holder, £3 each plus 12½% sales tax. Regrinds 30/-.

FISHING CRAFT FREQUENCIES

The following frequencies are held in stock: 6280, 4095, 4535, 2760, 2524 Kc. in FT243 holders. Immediate delivery.

We also manufacture—

Quotes on request.

CRYSTALS FOR TAXI AND BUSHFIRE SETS

SPECIAL

VACUUM MOUNTED CRYSTALS

for general communication frequencies in the range 3 to 14 Mc. Higher frequencies can be supplied.

BRIGHT STAR CRYSTALS may be obtained from the following Interstate firms: Messrs. A. E. Harrold, 123 Charlotte St., Brisbane; Gerard & Goodman Ltd., 192-196 Rundle St., Adelaide; A. G. Healing Ltd., 151 Pirie St., Adelaide; Atkins (W.A.) Ltd., 894 Hay St., Perth; Lawrence & Hanson Electrical Pty. Ltd., 56 Collins St., Hobart; Collins Radio, 408 Lonsdale St., Melbourne; Prices Radio, 5-6 Angel Place, Sydney.



The V.H.F. Group advises that it proposes to hold a convention on 8th March. It hopes to include a visit to the ARV Tx on Mt. Dandenong. Listen for further announcements.

The lecture for the meeting on 8th March will be given by the member of the staff of D.C.A. There will be no lecture at the April meeting as this is the annual general meeting, but there is to be a lecture on the same aspect of V.F. by a member of the staff of the Royal Melbourne Technical College for the May meeting. Ideas on lecture subjects would be welcomed by the President.

New members admitted at the meeting were: Full Members—K. C. Oldroyd (3ZED), A. Parker (3ARR), R. H. Hall (3ZEC), M. R. Osborne (3ZCZ), Associate Members—J. Forster, R. E. Buchanan, L. E. Fowler, W. H. Hemen; Country Junior Member—G. K. Glover.

EASTERN ZONE

Don't forget our Convention to be held at Sale, 15th and 16th March, so finalise your arrangements now.

The dinner will be held at the Masonic Hall, and on the Sunday there will be an inspection of Plastic Factories and 3G1. There will also be a picnic lunch at Sea Spray (weather permitting) and hidden tx hunts, etc., during the afternoon.

David 3DY were portable down at Point Lonsdale on 80 mx at the end of February.

SOUTH WEST ZONE

The zone is very active in most ways for the Convention, which is to be held in Warrnambool on 22nd and 23rd. If you intend coming, please send a deposit of £1 for food to reach the organiser, Bill Wines, 48 Crawley St., Warrnambool, before 8th March. You must also book your dinner for the Saturday dinner, which is a 3 course poultry meal with refreshments. Your booking should reach the organiser by 9th with a 10/- deposit.

There will be a prize for the chap who travels the longest distance. In addition there will be 144 Mc. activity and a fox hunt and tx hunt on 2.5.

The hook-ups have been well attended of late, even Peter 3APJ from Kyneton being present. Not much has been heard of late of 3HG, 3AFS or 3FA. What's the matter chaps, are you only able to find the switch for the Convention money? Well, if you are, you are 144 Mc. and 6 mx on the Saturday of the Convention to work the mobiles on these bands. We would also like a few beams turned on, but occasionally the 3.5 band and 3.5 mobiles will be able to have a contact as 3PS will be on the job from about 11 o'clock on the Saturday and perhaps 3AN. On arrival, you are all to report to the organiser's QTH for instructions of booking and a cup of tea. Trev. 3ATB and XYL and harmonics have been on the hook-ups, and 3AN has been on Warrnambool and I believe 3ANQ and he had a great rag chew on 144 Mc. equipment. We hope to see you down for the Convention.

The Ballarat boys never seem to come in on the hook-ups. What about it Don 3PO and Bob 3GR, and anyone else from that area? We do hope you will be down for the Convention. Kevin 3AKR made himself known the other week.

Geelong Amateur Radio Club

Geelong members are looking forward to the next Zone Convention to be held at Warrnambool on 22nd and 23rd March. Mr. C. Rann, 3AAK, while holidaying in Geelong called at the club and we were pleased to hear a talk on the subject of Amateur V.F.

VKS SOUTH WEST ZONE CONVENTION

to be held at
WARRNAMBOOL
on
SATURDAY AND SUNDAY,
22nd and 23rd MARCH, '58

★

For all bookings and enquiries
contact Organiser:
**Bill Wines, 48 Crawley Street,
Warrnambool**
before the 9th March.

The details of the flying spot scanner were discussed and the necessary techniques involved. Some members of the boys are advancing with Amateur V.F. transmission and wish to contact Melbourne experimenters. Would any Ham in Melbourne be interested in Amateur V.F. please contact Bill 3BU.

V.H.F. operators in the S.W. Zone please note. A meeting will be held at 1250 between 8th March, 1958, at the clubrooms, 191 Queen Street, for the purpose of discussing scoring and the necessary equipment. The meeting will be submitted in the form of a recommendation to Council. A picnic at some suitable rendezvous has been suggested for the following meeting.

Bob 3IC entertained members at a recent visit with a discussion on the 80-221 frequency meter. Recent disposal sales have been very successful and the necessary equipment have changed hands. Syllabus items for March are "Colour Tv. in America" and a visit to the shack of 3AWZ for V.H.F. operation.

MOORABBIN & DISTRICT RADIO CLUB

The New Year has got off to a flying start at Moorabbin, and it is hoped that this year will bring considerable progress in club activities. The general meeting in January consisted of a discussion on the various items considered ways of introducing new activities during the year. First and foremost, our aim is to get the club call 3APC heard more frequently on the 100-watt V.F. band. The meeting resolved that a hook-up night be held on 40 mx on the fourth Friday of each month. It was with this aim in mind that the resignation of our Treasurer, Ken 3ACE, who is shortly leaving us to go overseas on military service, was accepted. Ken was a G call sign, and we hope to hear him from this end. Meanwhile, we take this opportunity to thank him for his help in a very enjoyable trip and hope they get the most from their stay on the other side. The meeting elected Jack 3ZEP to act as Treasurer.

The first hook-up night was held on the fourth Friday night in January. At 2000 hours the club station, operated portable from the house of Laurie 3CH, called member stations and announced the programme. The President, Stan 3ZE, with the Vice-President, Jack 3ZEP, visiting. Altogether ten stations participated, including members from Kew, Kew 3YV and other guest stations. The evening was voted a great success, and we invite members and friends to join us next month at the same time.

Another activity in the near future is to be the first 3APC night from the club on the 100-watt V.F. band. The 3APC Plug-in equipment is being built by Jack 3ZEP and V.H.F. enthusiasts are requested to watch the progress. We also have a 3ZV on the Friday night in March, and each month thereafter, programme of technical lectures and visits is being arranged for the year. Don't forget to be with us the first and third Fridays of each month at the Library, Moorabbin Town Hall.

QUEENSLAND

During the month of January the boys have had a considerable number of things to consider. Present and future plans are being put to a good start and let's hope that our Division will grow in strength and prosper accordingly.

Vince 4VJ called to mind the enjoyable times that the boys had at our last Convention. His suggestion that we hold a local barbecue was an immediate decision to be made at a general meeting. Arrangements have been made for a get-together barbecue at Cash's home on Monday 1st on Monday 1st. All friends (and relatives) are requested to be at the Chermund Terminus by 2 p.m. Two mx beams are to be erected and the boys will run off. So come along and get in some practice for our next Annual Palm Beach Convention. Don't forget to bring along your radio gear, XYLs, and XYLs. Anyways, the good time is assured for all at a very nice picnic location.

Council wishes to remind all members that the next general meeting will be an Annual General Meeting, which brings with it nominations for positions on Council. At Townsville, there was a re-election of officers and I believe that there were no new faces present on the new Council. Let's hope that Brisbane with its greater population of Hams can give some of the present councillors a well-earned rest. There are some present councillors who have not been continuously for more years than they care to remember. Our Secretary, Jim 4PR, signified that he is willing to continue in the same position for a further year and believe me, we are all very grateful as the position is one which requires

a great deal of personal effort and sacrifice. As "Jim" would now be able to say, "You don't fine mate!"

The problem of securing a new typewriter has been temporarily solved. Mrs. 4PR has graciously consented to purchase a reasonable "QTC" stencil, which on a new machine will make for easy reading. We have received suggestions for a kind of portable typewriter, but the old Divisional typewriter, which Mrs. 4TO pounded with remarkable success, should now be used as the "coach!"

At the end of February, all membership fees will be due. The cost of production of "Amateur Radio" has risen 3/- per annum, and the cost of purchasing a reasonable "QTC" stencil, which on a new machine will make for easy reading. We have received suggestions for a kind of portable typewriter, but the old Divisional typewriter, which Mrs. 4TO pounded with remarkable success, should now be used as the "coach!"

On the Saturday night, following the Annual General Meeting, will be the Annual Dinner. The dinner will be held at the Anzac Hotel. All members who are able, are requested to attend. Friends from various Trade Houses and Government Departments will be invited to the dinner. We have an up to the minute lecture concerning the Geophysical Year by Professor Webster. For more complete details of the dinner and the opportunity for fellowship to any of the country boys who can join us at the Annual Dinner, further details will be published in "QTC".

The minutes of the recent General Convention have already been read and returned for further compilation. Also, we were once again requested to keep in mind the possibility of the Institute sending a representative to the General Convention next year. The estimated cost of such a trip abroad would be in the vicinity of £1,500, and with the possibility of our members making such a trip, it is suggested that we give this matter earnest consideration. Be prepared to make that little extra sacrifice, financially, to provide for the future.

Bert 3AO has been doing extensive maintenance to the 30 mx tx and on his holidays too. Just how keen can you get? Nevertheless, to reach the 30 mx band, he really brought 4W1 up to date. Council requests all Amateurs to make full use of their hands and brains to keep the 30 mx band populated. Latest reports are that the DX to the 30 mx band is now a boy has no trouble with signals to Japan on 30 Mc.

Righto boys! Start getting all that mobile gear ship-shape, as the Palm Beach Convention isn't far off. The Division hopes to secure a National Field Day, and the boys and fees, etc., will roughly correspond with those of previous years. The last Convention was a marvellous success and this year we hope to make it even better. So what about it if VKI boys can come all the way from Sydney to someone else's Convention, surely we can do it better.

Unfortunately, Stan 4SA was recently hospitalised with a bad arm. However, you can't keep a good one for long. Don't let Stan's arm making his presence felt, as was recently demonstrated by the number of students who are coming to the O.C. to see Stan. Let's hope to hear you're well enough to go back into harness, Stan.

The President advises that there is no new disposal to hand, but as there are a considerable number of Government surplus sales going through, anything may turn up. It is hoped to have a series of films shown at the future general meetings a series of film shows and technical lectures.

Is your rig V.F.? Does it comply with the regulations? Have you a frequency meter and your licence handy? These are questions you have to answer before you can go to the future and the Radio Inspector would like to have the right answers! You may be next.

Concluding with the request to listen for the numerous bands of 4000 and 4000 Hz on 108 Mc, please do not confuse these with the wedding bells that were heard recently by Jim 4W2, the Divisional Treasurer. To Jim and to Joyce, with all the wife that happiness can bring."

All Satellite reports are to be submitted to 4W1. See yer to-morrow Explorer!

MARYBOROUGH

4CB is operating on 10 mx only, while not watching 30 mx. He has a 70 ft. collapsible guved mast. 4DJ is staying up late for 15 mx DX, and getting some 30 mx DX. 4DJ is also operating on 10 mx and putting up a 7 Mc. ground-plane. Grahame made a portable rig for the

National Field Day, set up at Ghost Hill, Plain, and made some good contacts. He has also built a pre-selector which has brought up DX signals two 3 points. 4BG now has a 16 m converter and is enjoying DX on that band. In addition he is re-building grid dipper for extra bandwidth in order to adjust to the 1000 kHz. He is looking out to Noel Bignell, still at school, on getting his limited license. Get started on the c.b. Noel, so that we can hear you on the d.c. bands.

TOWNSVILLE

The Annual and General Meeting was held at the residence of 4BX and quite a large number turned up. In fact, although quite a few of the old timers were amongst the absent, nevertheless it was heartening to see a few new members roll along for nomination to the club.

The retiring officials were again duly re-elected and the Chairman and Secretary stating that this is their last term in office and some of the younger ones had better get ready to step into their shoes. Pat 4ZBO informed the club that the R.A.A.F. club was starting classes and issued an invitation to associate members to come along. Morse would also be attending and the club would enjoy his willingness to attend for Morse and tuition in Radio. Many thanks Pat.

Ted 4ZJ presented the balance sheet and all were relieved to find we were not in the red. Joe 4JR promises to give the long awaited last year's report and to come down at last. My apologies to Harry 4ZP at Sarina for not meeting him in Mackay as promised. Truth is the wife would not face the motor club and I am enjoying my trip. Eric 4EL and Len 4SD chasing the Europeans on 10 m each evening, closely watched and Ted 4ZJ going and coming on 10 m on holidays to Sydney and on the look out for parts for the gang. Bits and pieces hard to come by but I am sure they will be made. The beam due to birds building and hatching their eggs. Vern 4LK had a few hurried visits in course of business and now building mobile for the motor club. Harry 4ZP is looking to new QTH away from QRM. Bob 4NG watch out now. Bob 4TK also sends best wishes now.

A Christmas morning hook-up on 7 Mc, had Basil 4ZW, Harry 4ZP, Vic 4B, Bob 4TK, Vern 4LK, Alex 4MA, Frank 4FC, Claude 4UX and Frank 4FN. Andy 4BW was missing due to a cold and Harry 4ZP was out on the Douglas where he listened each day on sked times. Also spent some time at Atherton as guest of Harry 4ZP. The annual Christmas party was held on New Year's Day. Alex at Mt. Garnett spent part of his holidays in Cairns where he operated portable and then returned to Basil 4ZW in re-arranging his new rig. Basil crushed his little finger while doing chores around the house. Bob 4BW called on a few of the boys in the north whilst on his way and operated from some of them. Gordon 4GR of Maryborough was also a visitor to the north and called on several of the gang en route.

Harry 4HK and Bert 4BP have joined the morning or afternoon hook-up on 40 m at times. Likewise John 4DK, while Don 4PW has been heard since his return from Rocky on leave. Lesman 4Gion at Atherton has been running small office and home set-ups for 30 Mc. He has a new converter for his rx also. Why not try for a Z call sign again? Bob 4ZJ at last joined his all-band rig which has a multiband coupler. Tom 4AT and Andy 4BW in a 3-way with Eddie 50W on 10 m. Don 4PW and Harry 4ZP are now NNT getting settled in at Rabaul and expect his cases of junk to arrive from Mureeba at any time. The 4Z's are busy on 10 m on holidays and developed a passion for Nib. Qid. Mangos. While Harry 4ZP does the same for watermelons during the hot dry spell. 4ZG between Harry and Andy approaching the 1,500 mark. Ted 4MH (Cairns) comes on the air from time to time. Rumor has it that Ken 4SD is giving his rig away with his gear up for sale. Want to see some surplus gear just call on Bill 4XCM. He has a house full, no kidding.

SOUTH AUSTRALIA

There just cannot be many growls or complaints in our Division these days, because at the last get-together general business was at a minimum and many of the boys were on their way through, so that within the hour of opening the meeting, President John was able to hand over to those two hard working types, Douglas 4BP and Gordon 4GR, the running of the programme. This they did with great gusto and the amount of gear that changed hands was amazing. It was a pity that it was the keys (coupled with dust-for shame) to complete units.

These nights are usually well attended and this one was no exception. In spite of that there was a fair carry over, some of which went by private treaty and went away in new hamsheds.

Our membership is still growing, 7 new associates, and 2 new full members being added to the last meeting. There were a few conversions imminent too, when last exam. results are known, so Norm gets it both ways, or he gets you both ways, but in the mean time keep coming. Congratulations to the new faces, hope you enjoy the fraternity of membership.

The January holiday saw the annual picnic function again, this time Tree Gully being chosen, which turned out to be a really good choice, for it was apparent that all who attended had a most enjoyable time. In fact it was as good a picnic as we had ever had. Whether it was the compact nature of the facilities of the ground, the weather, the programme, or the organisers, something or a combination of them made a very friendly and enjoyable atmosphere, that gave the proceedings a swing that must have delighted Norm, Frank 3M2 and Luke 3LL, all of whom really put a lot into the show. We missed Joe 4ZB and some of the members who were at home could not make it—hope all well again now Joe.

The presentation of the items were perhaps illuminating in their way, for instance XYL of Treasurer Jim 3FO proved that she could throw a rolling pin further than King 3G could. As can be seen from that event, caused me some alarm—I'm now taking running lessons, to hand in my resignation to the D.F.C.

They had us threading needles, running bare footed over three-corner jacks, putting other bloated bones and finally playing cricket and in the latter event that portly character no less than "Fanny" (Aga Khan) 3FS was to start out didn't it seem to me. In fact it was considered his filters were wrong somewhere in that a fast one from John 3EBA just went through like any vigorous harrier would.

Phone once again cleaned the c.w. out, there being no need to quote scoring, that would be too painful. But the boys obviously do not confine their playing to W.I.A. picnic days.

Some hidden talents of a few of the younger members came to the fore, and it was a pleasure to see them in action. The final scores were c.w. all out for 30, with phone 8 for 10.

The c.w. boys were again very good. They did the children's misa out, "Uncle Frank Bentley" had a host of novel items and ideas, including an amiable bumble bee skeleton that was used as a rug and a good supply of minor prizes and plenty of ice-cream. The doll in the ice competition was won by the great grandchild of a dear old lady of 80 years of age was present and enjoying the proceedings, the little girl being John Hazeldine's youngest.

An inspection of the car of Len 5OC disclosed a spade for shovel—depends on your old school, and it was considered that by the one he used to dig them out of the QRM wharf, whereas in fact it is used to gather suitable garden soil. The trick being that if you dig out a bit of dirt and mix it with a little of the dirt—reason—his lives on a hillside where nature has denuded the rocks of soil and the dirt is a good garden soil.

By the way, it is possible that Len has the only set-up where the antenna leads go down the back of the car through the rear window, so what happens as a result of said hillside.

Bob 3BG has another unique set-up, his ant. being close to a h.c. vertical and he has 1 amp. r.f. and 1 amp. a.c. going up through the feeders and his own r.f. going up (quantity not quoted). What about beating something against the 1 amp. and poking side bands on to the 1 amp. main antenna?

The Gibber boys at 5WC are still on the ball. Pat 6JRXK recently joined the team with a couple of others who are c.w. types. We got your h.c. on Chap 10. The boys in Room 3FY building a new 50W rig around a Geleco and he tells us it will have plate and screen modulation. This time, good for him, better for us.

News from the South East tells that Col. 5CJ is in and on the way. He and the gang at Gambier took the form of a visit to the shack of 5CJ where a very enjoyable evening was spent. The evening was the part played by Mrs. 5CJ in providing an excellent supper. The appetites of the chaps being the best proof of the quality. The tape recording didn't work, but the boys were well received by the chaps also, and their thanks to the Division in making the tapes available.

John 5JA still off the air, for shame, for it's the one-eyed monster that still occupies his

time. Erg 5KU heard occasionally on 20 c.w. Stewart 5MS pokes out signal on 30 now and again, his daughter recently returning from U.K. with personal news of some of Stewart's G contacts.

TASMANIA

NORTH WESTERN ZONE

A record meeting was held at Burnie during February at the QTH of our President, Sid 78P. Twenty-four members were present, no less. A lively discussion took place on the pre-forms circulated by the Nolea Location Committee in Hobart and it was decided to make a 3-hour listening watch on Sunday 9th February from 9 a.m. to 12 midday in an attempt to correlate noise on the N.W. coast.

A practical demonstration of the Hon. Secretary's new coil winder followed after the meeting, and Ted 7EL performed his usual task as auctioneer.

The highlight of the evening was the supper provided by Sid's mother, ably assisted by his sister, Mrs. 78P, and by Roy 78N, Mrs. Bob Wilson and Miss Phyl Greaves. The usual comment applies and Sid should be able to make quite serious about this plan business and has obtained a pair of poles with the aid of a couple of bullocks. Believe bullocks will also be used to erect mast.

Alan 78P is receiving T.V. sound and although Alan has no working tube, the beam on the roof tops has given him increased social status in fact the whole street appears to be proud of it.

Lee 7KC heard by Sec. Max 78P calling him home. Since 7KC's return to the N.W. zone trouble was found out later Lee was calling on 30 m.

Ken 78P trip down South recently, worked portable from Hobart and was heard by Myle 78M on King Island. Thanks for report Myle. Taffed on 78A and found out why 78A sounded like a 30 m. Ken 78P is now working there Ken, and what about going into commercial production for beans, or do it for the money.

Burnie association Ken Brown seen at the local auction again; bought a telescope for 30/-, a 30 m. antenna and a 30 m. antenna. Associate Terry Tonga also visiting auction. That ARS was too dear anyway Terry.

HAMADS

1/- per line, minimum 3/-

Advertisements under this heading will only be accepted from Institute Members who desire to dispose of equipment which is their own personal property. Copy must be received by 15th of the month and remittance must accompany advertisement. Calculation of cost is based on an average of six words a line. Dealers' advertisements not accepted in this column.

FOR SALE: Eddystone 750 Receiver as new, had very little use, £100. Also a quantity of unused Ham gear including unused parts for a 1,000w. power supply, a Tecnico N80 crystal mic, an 813 valve and a host of other valves and equipment. Lee R. Dwyer, Newry, Gippsland, Vic.

FOR SALE: Ideal Mobiler, 4-wheel drive, ex-amphibious Jeep; 12 v. 60 amp. gen., excellent throughout. Reg. Sept. P. Ward, Highton, Geelong, Vic.

FOR SALE: "Television Broadcasting" by H. Chinn. As new, £44. Torrington, 4 Thistle St., South Pascoe Vale, Vic. FL 2324.

WANTED: "Radio and Television" 1947 containing details G8PO antenna loan, purchase. Geoff Morris, 181 Camberwell Rd., Camberwell, Vic. WB 5743.

Hamcraft

EVERYTHING IN RADIO AND TELEVISION

COLLARO TRANSCRIPTION TAPE RECORDER DECK £52/19/6

LANCO-GOLDING 4-Speed Transcription TURNTABLES, £39

TV AERIALS

Model 11 £8/1/0
 " 111 £8/4/0
 " 112 £9/10/0
 " 113 £12/5/0
 " 313 Super Fan £9/10/0
 " 300 Stabilt Ears £4/15/0
 "The Showman" De-Luxe Model
 Indoor Antenna £15/15/0 ea.
 300 Ohm Balanced Twin Feeder
 Lines 1/- per yard
 All types of TV Insulators in
 stock.
 TV Lightning Arrestors, 18/3 ea.

TV PARTS

E.H.T. Transformers, 17 or 21 in.
 17 in. Deflection Coil assy. £7/10/0
 21 and 21 in. Linearity Coil with
 Ferrite Rod £1/4/0
 17 or 21 in. Line and S.T.V.
 Chassis assy. comp. £32/11/0
 Ferracort TV Turret Tuner.
 £10/18/0
 Miniwatt Philips Turret Tuner.
 £18/5/0
 Q Plus MkII IF Strip £5/12/6
 Q Plus MkII IF Strip
 (limiter) £3/1
 Q Plus VPC 15-VPC 536 Video
 peening Colls 8/8 ea.

ALUMINIUM CHASSIS BLANK: T.C.R.

5 x 3 x 2 8/0
 6 x 4 x 2 9/1
 8 x 3 x 2 1/2 11/5
 10 x 6 x 2 1/2 14/8
 13 x 7 x 2 1/2 21/3
 11 x 8 x 2 1/2 17/5
 13 x 10 x 2 1/2 31/0
 17 x 8 x 3 37/0
 17 x 10 x 3 39/0
 17 x 12 x 3 52/7

FILTER CHOKES

C8/1 14H/50mA 32/0
 C5/1 10H/100mA 44/0
 C3/1 20H/100mA 30/0
 C1/1 20H/125mA 76/0
 C1/1 20H/150mA 92/0
 C1/1 20H/200mA 120/0

NOISE SUPPRESSORS

Ducan P.N. 351 0.1 x 0.1/200v.
 AC 100v. DC 15/4
 Ducan P.N. 436 for Remington
 Razor 7/0
 Ducan P.N. 435 (Mixmaster type) 7/0

Ducan P.N.T. 300 Auto Genera-
 tor Suppressor 1/5
 R.E.S. C.V40 100 pF. Reactor
 Variable Capacitors 17/4
 Servisol 1/2-pint tin 9/8

CAPACITORS Ceramic HI-KI Disc, subminiatur. 2.2 pF.-400 pF. 401 pF.-10,000 pF.

Ducan TV Capacitors
 500 pF./15kV 34/8
 50 x 50/250V 21/0
 200 pF./250V 34/5
 100 pF./250V 10/0
 U.C.C. Special "Dectroflash"
 630 pF./250V 46/7

Ducan Paper Capacitors

0.001-0.008 600 volt 1/5
 0.1/500 1/5
 0.02/400 2/0
 0.1/300 1/5
 0.05/270 1/5
 0.05/400 1/4
 0.5/500 1/7
 0.1/200 1/2
 0.1/400 1/0
 0.1/500 2/0
 0.25/200 2/5
 0.25/400 2/5
 0.25/600 3/11
 0.5/200 3/11
 0.5/400 3/11
 0.5/600 3/11

Variable Tuning Capacitors

A.W.A. Miniature (12-450 pF.)-
 2 gang 25/8
 3 gang 37/0
 A.W.A. Standard (11-430 pF.)-
 1 gang 22/0
 2 gang 25/0
 3 gang 30/0
 Roblin Midget type-
 1 gang 21/0
 2 gang 33/6
 2 gang with vernier 40/3
 3 gang plain 45/0
 3 gang with vernier 50/7
 Jubel 7-plate 8/2
 Jabel compression trimmers 1/8
 Philips air trim. (3-20 pF.) 1/6
 M.S.P. air trim. (3-20 pF.) 1/6

Incore Transformer

All prices subject to sales tax
 plus 25 per cent.
 T5/14 30 mA./150V/6.5 33/0
 T3/22 40 mA./270V/6.5 41/0
 T5/12 50 mA./230V/6.5 46/7
 T1/4 80 mA./285V/8.3 46/7
 T1/18 60 mA./285V/8.3 35/0
 T1/8 10 mA./285V/2 x 6.3 Sv. 55/0
 T1/29 80 mA./285V/2 x 6.3 Sv. 61/7
 T5/15 100 mA./285V/2 x 6.3 Sv. 61/7
 T5/23 160 mA./285V/2 x 6.3 Sv. 66/0
 T5/20 125 mA./285V/2 x 6.3 Sv. 66/0
 T5/28 125 mA./285V/2 x 6.3 Sv. 74/10
 T5/22 150 mA./285V/2 x 6.3 Sv. 79/7
 T5/24 200 mA./285V/2 x 6.3 Sv. 101/2
 T5/32 200 mA./285V/2 x 6.3 Sv. 114/3

Step-Down Incore Transformers

T3/14 230V./110V. 30 watt 55/0
 T1/30 230V./110V. 30 watt 82/0
 T1/50 230V./110V. 70 watt 95/11

Call in and see our Mr. SAM HURREY. Let him solve your HI-FI problems for you! We are Suppliers of LEAK, QUAD, ARMSTRONG, and WILLIAMSON (etc., etc.) equipment.

AMATEURS' BARGAIN CENTRE

HI-FIDELITY ELECTROSTATIC TWEETERS

Available now.
 Price on application.

JABEL ROTARY WAVE CHANGE SWITCHES

1 x 13 x 1 14/4 ea.
 2 x 13 x 1 24/4 ea.
 4 x 13 x 1 35/0 ea.
 4 x 8 x 1 14/4 ea.

OAK ROTARY WAVE CHANGE SWITCHES

1 x 11 x 3 11/10
 1 x 11 x 3 18/4
 1 x 11 x 3 25/7
 1 x 12 x 1 35/0
 1 x 12 x 2 21/4
 2 x 4 x 3 34/10
 2 x 10 HI-PI 1250 7 in. reels 11/7
 2 x 5 x 2 34/10
 2 x 5 x 3 34/10
 3 x 3 x 2 17/10
 3 x 3 x 3 24/10
 4 x 3 x 2 17/10
 4 x 2 x 3 24/10
 5 x 2 x 1 15/10
 5 x 2 x 2 25/10
 6 x 2 x 3 31/4

RECORDING TAPE

BASF 1200 7 in. reels 67/0
 BASF 1200 8 in. reels 65/0
 BASF 1700 7 in. reels 95/0
 Philips 1200 7 in. reels 70/0
 Philips 1800 ft. 7 in. reels 95/0
 Scotch 300 ft. 8 in. reels 28/0
 Scotch 620 ft. 8 in. reels 48/0
 Scotch 1200 ft. reels 70/0
 Westinghouse 1200 ft. 7 in. reels 67/0

TEST EQUIPMENT

Advance Q1 signal gen. £78/9/3
 Telecheck and marker generator £158/17/0
 Palco MX47 20,000 ohms voltm.
 multiplier £30/10/0
 Palco M22 10,000 ohms per volt
 multimeter £17/10/0
 Palco ET44 valve tester £37/10/0
 University TVR-EV electronic
 volt meter £40
 University TV30 30kv. probe for
 TVR-EV £8/5/0
 University TV7 crystal RF probe
 for TVR-EV £5/0/0
 University TV7 valve RF probe
 for TVR-EV £78/0/0
 University TVR-PG pattern gener-
 ator £80
 University B.T.B. dry battery
 tester £16/10/0
 University U.B.A. uniscope (re-
 sistence and capacitance tester) £34
 University MVA2 AC/DC multi-
 meter £17/10/0
 G.R.A. de luxe test leads 10/3
 "abel probe" 10/3
 Westinghouse meter rectifier 5
 mA. 35/0
 Westinghouse meter rectifier 1
 mA. (all prices subject 12 1/2% tax).

SOCKET PUNCHES

(Hammer or screw type)
 1-3/16 Std. 45/4
 1 in. Curv. act. 30/4
 2 1/4 in. Invol. 38/3
 2 1/2 in. button case 23/3
 1/2 in. for pots, bezels, etc. 25/0
 "BIB" wire strippers 6/0
 L.T. 83 Westinghouse 6/12V. 3A.
 battery charger rectifiers 70/0

290 LONSDALE STREET, MELBOURNE

FB 3711

Been to an ORCHESTRAL CONCERT lately?

PARDON OUR ASKING, but the quality of sound which quite a lot of people appear to find satisfactory makes us wonder if they have ever heard an orchestra "in the flesh". If you are thinking of buying a new loudspeaker, or even if you're not for that matter, why not spend just a few shillings on refreshing your memory as to what an orchestra really sounds like? If you find it free of the booming bass and tizzing treble which has probably become associated in your mind with much audio equipment you will be in the right frame of mind to appreciate the VITAVOX DU120 DUPLEX COAXIAL LOUDSPEAKER—the loudspeaker which adds so little to the original sound.

VITAVOX

DU 120 DUPLEX COAXIAL
FULL RANGE
LOUDSPEAKER



RETAIL PRICE £49-6-3

Available from all Wholesale Houses

**Sole Australian Factory
Representatives:**

R. H. CUNNINGHAM PTY. LTD.

8 BROMHAM PLACE, RICHMOND, E.1, VIC. Phone: JB 1614. Cable: "Cunnig" Melbourne.
16 ANGAS ST., MEADOWBANK, N.S.W. Phones: WY 0316, WY 3852. Cable: "Cunnig" Sydney.